

PELICAN BAY SERVICES DIVISION
Municipal Services Taxing & Benefit Unit

NOTICE OF PUBLIC MEETING

SEPTEMBER 2, 2020

THE **WATER MANAGEMENT COMMITTEE** OF THE PELICAN BAY SERVICES DIVISION WILL MEET AT **3:00 PM** ON **WEDNESDAY, SEPTEMBER 2** AT THE BOARD OF COUNTY COMMISSIONERS CHAMBERS, THIRD FLOOR, COLLIER COUNTY GOVERNMENT CENTER, 3299 TAMIAMI TRAIL EAST, NAPLES, FL 34108.

AGENDA

1. Pledge of Allegiance
2. Roll call
3. Agenda approval
4. Approval of 1/23/20 meeting minutes
5. Audience comments
6. Lake bank remediation update on Lake 2-9
7. Detailed review of ABB Oakmont Lake proposal
8. Update on ABB's estimates on next 2 potential lakes in Bridgeway
9. Drainage pipes and stormwater easement management options
10. Other committee member comments
11. Adjournment

**indicates possible action items*

ANY PERSON WISHING TO SPEAK ON AN AGENDA ITEM WILL RECEIVE UP TO THREE (3) MINUTES PER ITEM TO ADDRESS THE BOARD. THE BOARD WILL SOLICIT PUBLIC COMMENTS ON SUBJECTS NOT ON THIS AGENDA AND ANY PERSON WISHING TO SPEAK WILL RECEIVE UP TO THREE (3) MINUTES. THE BOARD ENCOURAGES YOU TO SUBMIT YOUR COMMENTS IN WRITING IN ADVANCE OF THE MEETING. ANY PERSON WHO DECIDES TO APPEAL A DECISION OF THIS BOARD WILL NEED A RECORD OF THE PROCEEDING PERTAINING THERETO, AND THEREFORE MAY NEED TO ENSURE THAT A VERBATIM RECORD IS MADE, WHICH INCLUDES THE TESTIMONY AND EVIDENCE UPON WHICH THE APPEAL IS TO BE BASED. IF YOU ARE A PERSON WITH A DISABILITY WHO NEEDS AN ACCOMMODATION IN ORDER TO PARTICIPATE IN THIS MEETING YOU ARE ENTITLED TO THE PROVISION OF CERTAIN ASSISTANCE. PLEASE CONTACT THE PELICAN BAY SERVICES DIVISION AT (239) 597-1749 OR VISIT PELICANBAYSERVICESDIVISION.NET.

**PELICAN BAY SERVICES DIVISION
WATER MANAGEMENT COMMITTEE MEETING
JANUARY 23, 2020**

The Water Management Committee of the Pelican Bay Services Division met on Thursday, January 23 at 1:30 p.m. at the SunTrust Bank Building, 801 Laurel Oak Drive, Suite 302, Naples, FL 34108. The following members attended.

Water Management Committee

Denise McLaughlin, Chair
Tom Cravens

Jacob Damouni (*absent*)

Michael Weir

Pelican Bay Services Division Staff

Neil Dorrill, Administrator
Chad Coleman, Operations Manager
Lisa Jacob, Project Manager

Alex Mumm, Sr. Field Supervisor (*absent*)

Barbara Shea, Interim Operations Analyst

Also Present

Jim Carr, Agnoli, Barber & Brundage
Susan O'Brien, PBSB Board

APPROVED AGENDA (AS PRESENTED)

1. Pledge of Allegiance
2. Roll call
3. Agenda approval
4. Approval of 11/21/19 meeting minutes
5. Audience comments
6. Current projects
 - a. St. Maarten/St. Thomas Lake 2-9
 - b. Bay Colony Beach Dune Swale
 - c. Grosvenor/Dorchester drainage basin
7. Prioritizing lake bank restoration projects for next FY21 budget
8. Review of Pollution Control Report
9. Review of algae problem in target lakes
10. Other committee member comments
11. Adjournment

ROLL CALL

Mr. Damouni was absent and a quorum was established

AGENDA APPROVAL

Mr. Cravens motioned, Mr. Weir seconded to approve the agenda as presented. The motion carried nnanimously.

APPROVAL OF 11/21/19 MEETING MINUTES

Mr. Cravens motioned, Mr. Weir seconded to approve the 11/21/19 meeting minutes as presented. The motion carried unanimously.

AUDIENCE COMMENTS

Ms. O'Brien requested that Mr. Dorrill provide the PBSB Board with an update on the Operations Analyst Position and "who's doing what" by the existing staff during this interim period.

CURRENT PROJECTS

ST. MAARTEN/ST. THOMAS LAKE 2-9

Ms. Jacob commented that the Lake 2-9 lake bank restoration project is scheduled to begin in April.

BAY COLONY BEACH DUNE SWALE

Ms. Jacob reported that the Bay Colony Beach Dune Swale project is out for bid; bids are due back on Feb. 12.

GROSVENOR/DORCHESTER DRAINAGE BASIN

Ms. Jacob commented that she expects our ABB engineer, Mr. Jim Carr, to finalize the design plans for the Grosvenor/Dorchester drainage basin project by tomorrow. Once received, she will put the project out for bid. Mr. Dorrill commented that the project will include mahoe removal only in areas affecting the re-alignment of the swale.

Ms. O'Brien asked for clarification on the length of time and complexity of this project. Ms. McLaughlin suggested that when the drainage pipes were unblocked, unnatural drainage flows were created, causing additional work to be needed.

PRIORITIZING LAKE BANK RESTORATION PROJECTS FOR FY21 BUDGET

The committee reviewed and discussed the prioritized list by critical need of lake bank remediation of our PB lakes, which was created by ABB a few years ago. Mr. Carr commented that he estimates costs of remediation have risen by approximately 40% since this list was created. The committee and staff tasked Mr. Carr to update the estimated cost of remediation for the top 7 lakes on the list (omitting Lake 2-9 for which a project is currently in process). Mr. Coleman noted that lakes 1-6, 4-1, and 2-5 are on our list of targeted algae lakes and in the top 10 of our prioritized lake bank remediation list. Mr. Carr suggested that it would be worthwhile to do a walk around all of our lakes to determine whether any of the lake bank conditions have changed.

Mr. Dorrill commented that he will contact Mr. Dave Mangan, General Manager of the Club Pelican Bay golf course, to determine whether he feels we should address lake bank remediation of lakes 2-8 and 4-11 (within the golf course) in light of the recent golf course restoration work.

**Pelican Bay Services Division Water Management Committee Meeting
January 23, 2020**

Ms. O'Brien suggested that we consider asking an engineer from the South Florida Water Management District to do a walk around at the top seven lakes that are under our consideration for lake bank remediation and share with us what they are expecting us to do relative to our permits. Mr. Dorrill commented that he is not interested in doing this.

Ms. O'Brien commented that the board has had discussions to bundle lake bank projects and include these into our upcoming large project financing package.

REVIEW OF POLLUTION CONTROL REPORT

Ms. McLaughlin reported that she recently had a meeting with Mr. Coleman, Mr. Mumm, and Ms. Jacob to discuss the report of recommendations to improve water quality, prepared by the County's Pollution Control Dept. A list of all the recommendations along with (1) priority, (2) staff required, (3) doing now?, (4) cost, (5) complexity, and (6) a proposed plan for each item was included in the agenda packet. The committee and staff discussed the first 11 items on the list, and follow up that was agreed upon is as follows:

- Mr. Dorrill will look into the feasibility of bagging grass clippings.
- The possibility of the PBF employing an inspector that safeguards against water quality impacts to the stormwater system could be included for discussion at a future PBF/PBSD workshop. The committee suggested that the PBF would be the more appropriate entity to take on this responsibility as they have enforcement capability.
- Mr. Dorrill will ask staff to identify a test lake to plant littoral plants to study whether these plants will cause a reduction in algae.
- Mr. Dorrill will contact the Grey Oaks community to obtain information on the device they are using to mechanically remove algae.
- Mr. Coleman will determine whether all of our lakes with algae problems have aerators installed.
- Ms. Jacob will contact our environmental consultant, Mr. Jeremy Sterk, to determine whether he would be able to systematically determine whether our aerators are causing algae reduction in our lakes.

ADJOURNMENT

The meeting was adjourned at 2:59 p.m.

Denise McLaughlin, Chair

Minutes approved [] *as presented* OR [] *as amended* ON _____] *date*

DRAFT

**AGNOLI
BARBER &
BRUNDAGE, INC.**
Professional Engineers, Planners, Surveyors & Landscape Architects

PELICAN BAY



Lake 4-1 Analysis

DRAFT



Background

Erosion can be defined as the gradual removal or movement of soil from one area to another caused by water, wind, or other natural causes. Lake bank erosion is very common in southwest Florida due to the variance in seasons it faces. It can be caused by strong winds that damage the shoreline such as in events like Hurricane Irma and overland runoff.

A site visit was conducted on August 6th, 2020 for lake 4-1 at Pelican Bay to measure erosion and assess the condition of the lake banks. Even though all indications of erosion are noted when conducting site visit, the primary form of analytical data that is taken to determine the degree of erosion are measurements of both escarpment height and slope. Escarpment height can be defined as any sudden drop-off that separates the lake bank from the elevation just inside the water's edge. It is important to note that drop-offs are common for any lake however anything over 9 inches exceeds the permitted threshold for the South Florida Water Management District (SFWMD) permit. The slope can be defined as the degree of inclination of the ground. The slope is an indicator of erosion because the slope determines the rate at which water flows over the top of lake banks, its action will accelerate the process of erosion. Like the escarpment height, there is a permitted limit of how steep the slope may be. Any slope greater than 4:1, meaning a length of four feet for every foot in depth, is considered out of compliance with the SFWMD permit.

Wind is a major factor in creating waves, fortunately for Lake 4-1 the longest distance from the east to the west side of the lake is about 260 linear feet however the length from north to south is quite significant. Approximately 2600 linear feet separates the north and south sides of the lake, leaving it prone to erosion. Incoming cold fronts and increased wind from storms can create waves that worsen the condition of the lake banks and create additional problems. The long fetch allows the waves to build up energy before crashing into the lake bank requiring a more robust and reinforced shoreline.



DRAFT



Analysis

Lake 4-1 is bound by Green Tree Drive to the west and Oakmont Parkway to the east. The lake is surrounded by residential properties and a greenway on the east side of the lake bank. The rooftops, roads, and greenway along the lake banks act as impervious surfaces that prevent runoff from percolating into the ground, producing runoff directed to the lowest point of elevation which is the lake. To reduce erosion, the optimal solution is to have a drain or structure to collect and control the flow of the water, however in this case, majority of rainfall flows directly into Lake 4-1. The consistent flowing of water over the lake bank runs down the surface weakening and deteriorating the soil allowing ledges and steep slopes to form.

Some of the depth found around the lake banks during inspection can be attributed to geo-tube put in place from previous erosion prevention effort. This geo-tube anchors much of the soil to the bank and holds the soil in place as water runs over it. This allows the part of the bank not held in place by the fabric sock to be pushed farther into the lake. The geo-tube then begins to fail and slide into the lake itself, no longer serving its purpose.



DRAFT

The pedestrian side has some steep side slopes abutting the lake bank that need to be remediated to meet the 4:1 slope requirement. Excess runoff produced by the roofs of the homes may contribute to this issue however the homes on the east side, abutting the pathway, should have downspouts connected into the storm water system along the roads in front of the homes.

The escarpment height around much of the lake was higher than the 9-inch limit for the SFWMD permit showing critical signs of erosion along the bank, reaching depths of up to 30 inches in some places. It was most critical along the east side of the lake where you can see exposed geo-tube from previous erosion prevention efforts. However, this fabric has begun to fail and is now sliding into the water no longer preventing erosion along the bank.

There is an outfall structure on the north side of the lake bank that showed signs of erosion behind the headwall. Typically, headwall is used to stabilize the soil around drainage structures to prevent the structure from falling into the water. In the picture below, the headwall has been exposed due to the receding lake bank. This presents not only a problem of erosion but may put the structure at risk in the long-term.



DRAFT



Financial Summary

Given the amount of lake bank Lake 4-1 provides, there are different restoration options depending on expenses and degree of erosion. Generally, there are two methods of restoration, installing a Geoweb system or simply regrading the existing lake bank to comply with the standards.

Geoweb is a three-dimensional system made up of interconnected cells that reinforces the lake bank due to the infill inside of these cells. The type of infill selected depends on the extent of the erosion, however in this case, compacted soil would be used. This will allow vegetation to grow through the cells keeping the aesthetic view of a natural lake. This would require minimal maintenance however it would out-weigh the cost of severe erosion. The other option is to re-grade the existing lake bank to restore it to the permitted conditions. This can also be done with the installation of additional fill. However, it must be noted that only regrading the lake bank will delay the critical erosion rather than prevent it. Without a prevention method in place, this issue will occur over time.

The field data collected in Appendix A, determines that there are areas that are more severe than others. Therefore, different options regarding the extent of restoration has been provided below. For further financial information, refer to the tables in Appendix B.

Option A

Throughout Lake 4-1, the most common form of erosion is the escarpment height which exceeds 9-inches failing to comply with the SFWMD permit. However, there are areas where slope and the escarpment height are both an issue, specifically the southeast corner of the lake. As seen in Appendix A, this would be the most minimal amount of restoration (approximately 550 linear feet).

Option B

Eventually, the entire lake will have to be restored so doing larger portions at a time will most likely work more efficiently and effectively. Comparing the east and west side of the lake,



DRAFT



the east side has steeper slopes as well as deeper drops. Option B presents restoring the east side in its entirety which will be more expensive however will prevent problems in the future as well as avoid continuous construction.

Option C

Option C proposes restoring the entirety of Lake 4-1. While this may be beneficial in avoiding multiple periods of construction, this will require a significant cost which would most likely not appeal to the community.



Appendix A

LEGEND

To Be Repaired :


Option A Option B Option C

MEASUREMENTS:

Slope: Any slope greater than 4:1 (EX. 3:1) exceeds the permitted design (Red).

Escarpment Height: Drop greater than 9 inches is considered out of compliance with SFWMD permit (Red).

DRAFT



OPTION A

Preliminary Budget Estimate

Item No.	Description	Unit	Quantity	Unit Cost	Total Cost
----------	-------------	------	----------	-----------	------------

GEO-WEB SYSTEM

1	Mobilization	LS	1	\$ 3,000	\$ 3,000
2	Landscape Replacement (Sod, Native Vegetation) (10' wide x 550 LF)	SF	5,500	\$ 3	\$ 16,500
3	Irrigation Replacement in impacted areas (10' wide x 550 LF)	SF	5,500	\$ 2	\$ 11,000
4	Littoral Plantings @ 2 per linear foot of modified lake bank	EA	1,100	\$ 4	\$ 4,400
5	In Place Compacted, Imported Fill ((550 LF x 2' x 8')x2)/27=652 CY	CY	652	\$ 100	\$ 65,200
6	Silt Fence	LF	550	\$ 2	\$ 1,100
7	Turbidity Barrier	LF	600	\$ 30	\$ 18,000
8	Yard Drain Connections @ approx. 2 per lot/home (includes ADS 12" Yard Drain)	EA	4	\$ 1,000	\$ 4,000
9	Sandy Top Soil with 10%-12% Organics (3" deep over impacted areas) (550 LF x 8' x 3")	CY	41	\$ 100	\$ 4,074
10	GeoWeb - GW 30V3 (12' wide) (Includes backfill, 57 stone, anchors, non-woven fabric)	SF	6,600	\$ 15	\$ 99,000

GRAND TOTAL	=	\$ 226,274
--------------------	---	------------

RE-GRADE

Without Additional Fill

1	Mobilization	LS	1	\$ 3,000	\$ 3,000
2	Landscape Replacement (Sod, Native Vegetation) (10' wide x 550 LF)	SF	5,500	\$ 3	\$ 16,500
3	Irrigation Replacement in impacted areas (10' wide x 550 LF)	SF	5,500	\$ 2	\$ 11,000
4	Littoral Plantings @ 2 per linear foot of modified lake bank	EA	1,100	\$ 4	\$ 4,400
5	Silt Fence	LF	550	\$ 2	\$ 1,100
6	Turbidity Barrier	LF	600	\$ 30	\$ 18,000
7	Yard Drain Connections @ approx. 2 per lot/home (includes ADS 12" Yard Drain)	EA	4	\$ 1,000	\$ 4,000

GRAND TOTAL	=	\$ 58,000
--------------------	---	-----------

RE-GRADE OPTION With Additional Fill

8	In Place Compacted, Imported Fill ((550 LF x 2' x 8')x2)/27=652 CY	CY	652	\$ 100	\$ 65,200
---	--	----	-----	--------	-----------

GRAND TOTAL	=	\$ 123,200
--------------------	---	------------

Note: Estimated costs are pre-survey and are approximate. Cost estimates do not include survey, site permitting or design plans.

DRAFT

OPTION B

Preliminary Budget Estimate

Item No.	Description	Unit	Quantity	Unit Cost	Total Cost
----------	-------------	------	----------	-----------	------------

GEO-WEB SYSTEM

1	Mobilization	LS	1	\$ 3,000	\$ 3,000
2	Landscape Replacement (Sod, Native Vegetation) (10' wide x 2800 LF)	SF	28,000	\$ 3	\$ 84,000
3	Irrigation Replacement in impacted areas (10' wide x 2800 LF)	SF	28,000	\$ 2	\$ 56,000
4	Littoral Plantings @ 2 per linear foot of modified lake bank	EA	5,600	\$ 4	\$ 22,400
5	In Place Compacted, Imported Fill ((2800 LF x 2' x 8')x2)/27=3319 CY	CY	3,319	\$ 100	\$ 331,900
6	Silt Fence	LF	2,800	\$ 2	\$ 5,600
7	Turbidity Barrier	LF	100	\$ 30	\$ 3,000
8	Yard Drain Connections @ approx. 2 per lot/home (includes ADS 12" Yard Drain)	EA	80	\$ 1,000	\$ 80,000
9	Sandy Top Soil with 10%-12% Organics (3" deep over impacted areas) (2800 LF x 8' x 3')	CY	207	\$ 100	\$ 20,741
10	GeoWeb - GW 30V3 (12' wide) (Includes backfill, 57 stone, anchors, non-woven fabric)	SF	33,600	\$ 15	\$ 504,000

GRAND TOTAL	=	\$ 1,110,641
--------------------	---	---------------------

RE-GRADE

Without Additional Fill

1	Mobilization	LS	1	\$ 3,000	\$ 3,000
2	Landscape Replacement (Sod, Native Vegetation) (10' wide x 2800 LF)	SF	28,000	\$ 3	\$ 84,000
3	Irrigation Replacement in impacted areas (10' wide x 2800 LF)	SF	28,000	\$ 2	\$ 56,000
4	Littoral Plantings @ 2 per linear foot of modified lake bank	EA	5,600	\$ 4	\$ 22,400
5	Silt Fence	LF	2,800	\$ 2	\$ 5,600
6	Turbidity Barrier	LF	100	\$ 30	\$ 3,000
7	Yard Drain Connections @ approx. 2 per lot/home (includes ADS 12" Yard Drain)	EA	80	\$ 1,000	\$ 80,000

GRAND TOTAL	=	\$ 254,000
--------------------	---	-------------------

RE-GRADE OPTION With Additional Fill

8	In Place Compacted, Imported Fill ((2800 LF x 2' x 8')x2)/27=3319 CY	CY	3,319	\$ 100	\$ 331,900
---	--	----	-------	--------	------------

GRAND TOTAL	=	\$ 585,900
--------------------	---	-------------------

Note: Estimated costs are pre-survey and are approximate. Cost estimates do not include survey, site permitting or design plans.

DRAFT

OPTION C

Preliminary Budget Estimate

Item No.	Description	Unit	Quantity	Unit Cost	Total Cost
----------	-------------	------	----------	-----------	------------

GEO-WEB SYSTEM

1	Mobilization	LS	1	\$ 3,000	\$ 3,000
2	Landscape Replacement (Sod, Native Vegetation) (10' wide x 5600 LF)	SF	56,000	\$ 3	\$ 168,000
3	Irrigation Replacement in impacted areas (10' wide x 5600 LF)	SF	56,000	\$ 2	\$ 112,000
4	Littoral Plantings @ 2 per linear foot of modified lake bank	EA	11,200	\$ 4	\$ 44,800
5	In Place Compacted, Imported Fill ((5600 LF x 2' x 8')/27=6637 CY	CY	6,637	\$ 100	\$ 663,700
6	Silt Fence	LF	5,600	\$ 2	\$ 11,200
7	Turbidity Barrier	LF	100	\$ 30	\$ 3,000
8	Yard Drain Connections @ approx. 2 per lot/home (includes ADS 12" Yard Drain)	EA	76	\$ 1,000	\$ 76,000
9	Sandy Top Soil with 10%-12% Organics (3" deep over impacted areas) (5600 LF x 8' x 3")	CY	415	\$ 100	\$ 41,481
10	GeoWeb - GW 30V3 (12' wide) (Includes backfill, 57 stone, anchors, non-woven fabric)	SF	67,200	\$ 15	\$ 1,008,000

GRAND TOTAL	=	\$ 2,131,181
--------------------	----------	---------------------

RE-GRADE

Without Additional Fill

1	Mobilization	LS	1	\$ 3,000	\$ 3,000
2	Landscape Replacement (Sod, Native Vegetation) (10' wide x 5600 LF)	SF	56,000	\$ 3	\$ 168,000
3	Irrigation Replacement in impacted areas (10' wide x 5600 LF)	SF	56,000	\$ 2	\$ 112,000
4	Littoral Plantings @ 2 per linear foot of modified lake bank	EA	11,200	\$ 4	\$ 44,800
5	Silt Fence	LF	5,600	\$ 2	\$ 11,200
6	Turbidity Barrier	LF	100	\$ 30	\$ 3,000
7	Yard Drain Connections @ approx. 2 per lot/home (includes ADS 12" Yard Drain)	EA	76	\$ 1,000	\$ 76,000

GRAND TOTAL	=	\$ 418,000
--------------------	----------	-------------------

RE-GRADE OPTION With Additional Fill

8	In Place Compacted, Imported Fill ((5600 LF x 2' x 8')/27=6637 CY	CY	6,637	\$ 100	\$ 663,700
---	---	----	-------	--------	------------


GRAND TOTAL	=	\$ 1,081,700
--------------------	----------	---------------------

Note: Estimated costs are pre-survey and are approximate. Cost estimates do not include survey, site permitting or design plans.

DRAFT

Appendix C- Southeast Corner


DRAFT



East

DRAFT


Agenda Item #7
Page 12 of 13




West

DRAFT

Agenda item #7
Page 13 of 13





Agenda Item #8
Page 1 of 6

DATE: 07-11-13	SHEET: 01	PROJECT: 0235.6	DESIGNED BY: TH	DRAWN BY: TTT	DATE: 04-03-13
FILE: IP_BASIN 1					

TURRELL, HALL & ASSOCIATES, INC.
Marine & Environmental Consulting
3584 Exchange Ave. Suite 13,
Naples, FL 34109-3732
Phone: (239) 643-0166
Fax: (239) 643-6632
email: tom@turrellhall.com

CLAM BAY NUTRIENT MANAGEMENT
BASIN 1



LEGEND
 PRIVATE LAKES



Agenda Item #3
 Page 2 of 6

DATE: 07-11-13	NO. SHEETS: 02	SHEET: 02
PROJECT: 0235.6	CLIENT: RMJ	DESIGNED BY: TTT
LOCATION: IP BASIN 2		

TURRELL, HALL & ASSOCIATES, INC.
 Marine & Environmental Consulting
 3584 Exchange Ave. Suite B,
 Naples, FL 34104-3732
 Phone: (239) 643-0166
 Fax: (239) 643-6602
 email: tom@turrellhall.com

CLAM BAY NUTRIENT MANAGEMENT
BASIN 2




Agenda Item #8
Page 3 of 6

DATE: RMJ	REVISED: TTT	NO. OF SHEETS: 03
PROJECT: TH	SHEET: 03	
DATE: 07-11-13		
PROJECT: IP_BASIN 3		

TURRELL, HALL & ASSOCIATES, INC.
 Marine & Environmental Consulting
 3584 Exchange Ave., Suite 10
 Naples, FL 34108-3732
 Phone: (239) 643-0166
 Fax: (239) 613-6682
 email: tana@turrell-associates.com

CLAM BAY NUTRIENT MANAGEMENT
BASIN 3



LEGEND
PRIVATE LAKES



Agenda Item #3
Page 4 of 5

DATE: 07-11-13	REVISED: 04	BY: TTT	DATE: 04/11/13	REVISION:
PROJECT: 0235.6				
CLIENT: RMJ				
FILE: IP_BASIN 4				

TURRELL, HALL & ASSOCIATES, INC.
Marine & Environmental Consulting
3584 Exchange Ave. Suite 111
Naples, FL 34104-3732
Phone: (239) 643-0166
Fax: (239) 643-6632
email: tna@turrell-associates.com

CLAM BAY NUTRIENT MANAGEMENT
BASIN 4




Agenda Item #8
Page 5 of 6

DATE:	RMJ	REVISED:	TTT
PROJECT:	TH	SHEET:	05
DATE:	07-11-13		
PROJECT:	IP_BASIN 5		

TURRELL, HALL & ASSOCIATES, INC.
 Marine & Environmental Consulting
 3584 Exchange Ave. Suite B,
 Naples, FL 34104-3732
 Phone: (239) 643-0166
 Fax: (239) 643-6632
 email: th@turrellhall.com

CLAM BAY NUTRIENT MANAGEMENT
BASIN 5




DATE: RMJ	REVISION: TTT	NO.	DATE	DESCRIPTION
PROJECT: 0235.6	06	1		
DATE: 07-11-13		2		
USER: JP_BASIN 6		3		

TURRELL, HALL & ASSOCIATES, INC.
 Marine & Environmental Consulting
 3584 Exchange Ave. Suite B3,
 Naples, FL 34106-3723
 Phone: (239) 643-0166
 Fax: (239) 643-6632
 email: tnh@turrell-associates.com

CLAM BAY NUTRIENT MANAGEMENT
BASIN 6

Reach	Latitude	Community	Acre ft	Partner (Acres)	Partner to be Replaced	Average Depth (ft)	Maximum Depth (ft)	Maximum Height (ft)	Average Slope	Max Slope	Critical Depth (ft)	Natural Area (Acres)	Riprap (Acres)	Wall (Feet)	Units	Density (ft per ft)	Box Types	Structural Protection (ft)	Restored (ft)	Final State
4.1	294360	Quinner Park	7.49	5489	5489	1.7	2.6	4.11	2.51	2.51	975				37	154	1	1	1	3
1.3	202351	Bridge Way / Terra Mar	4.65	3,232	1,646	1.4	2.1	4.21	2.51	2.51	606	1,277			22	75	0	1	1	3
3.3	114242	St. Anthony/Parish School / Good Pointe	2.84	2,645	2,200	1.5	2.3	3.91	2.31	2.31	2,183	445			40	55	1	2	1	4
2.9	57254	St. Anthony / St. Thomas	1.31	1,659	1,250	2.3	2.9	4.11	2.31	2.31	640	274	1.41	269	132	9	1	2	1	4
2.8	46278	Pelican Bay Golf	1.26	1,354	1,254	1.8	2.7	4.61	2.11	2.11	640				8	269	1	1	3	2
1.6	172452	Bridge Way / Terra Mar	3.27	3,090	1.4	2.3	2.3	4.41	2.61	2.61	291	110		283	26	119	1	2	1	3
2.5	130180	Georgetown	2.99	2,671	2,542	1.8	2.2	3.91	2.61	2.61	301				49	36	1	1	3	3
5.5	112288	Georgetown	2.27	1,779	1,779	1.3	1.8	3.61	2.61	2.61	1,397				8	127	1	2	3	4
2.3	94409	Edgewood Park	2.19	2,132	1,815	1.4	2.8	3.81	2.71	2.71	62	1,110			205	9	0	3	2	2
4.1	130314	Pelican Bay Golf	2.89	2,706	2,423	1.9	2.4	3.11	2.71	2.71	274				135	185	1	3	2	2
1.8	15715	Wildcat Astoria	0.36	619	214	1.8	1.4	2.71	2.71	2.71	922			85	106	2.0	1	3	2	2
4.1	110494	Pelican Bay Golf	2.24	2,242	1,820	1.2	2.6	4.11	2.11	2.11	922				16	201	1	3	1	3
2.1	177262	Chimborazo Meadows	0.41	323	491	1.2	1.8	4.51	4.41	4.41	122				122	3	1	2	3	3
2.7	195042	Pelican Bay Golf	4.26	4,262	3,778	1.2	2.3	4.21	4.01	4.01	220	634			93	40	1	3	2	2
4.3	124698	Pelican Bay Golf	2.86	2,441	2,049	1.9	2.4	3.61	2.91	2.91	1,407	372			6	345	1	3	3	3
5.2	132291	Unalaska of Pelican Bay	2.26	2,279	1,740	1.5	1.9	3.21	2.71	2.71	160	829			160	32	0	2	3	3
5.3	113107	Annie	2.68	1,524	1,524	1.5	1.8	4.11	2.31	2.31					84	38	1	2	3	3
3.6	46715	Pelican Bay Golf	1.07	896	644	1.7	2.1	3.31	10.91	10.91	1,277	322			30	22	0	3	3	1
3.7	52314	Pelican Bay Golf	1.22	1,266	1,046	1.6	1.9	7.41	5.21	5.21	839				46	33	0	3	2	3
4.7	202360	Pelican Bay Golf	0.70	846	846	1.6	1.9	5.91	3.81	3.81	635				4	222	0	2	2	2
3.1	86391	Oak Lake Sanctuary	2.54	2,077	1,972	0.9	1.5	2.41	1.41	1.41	105				18	110	1	2	2	2
4.9	42224	Pelican Bay Golf	0.97	788	610	1.5	2.0	7.21	5.21	5.21	348	179			49	22	0	3	3	1
1.7	97922	Wildcat Astoria	0.91	1,388	1,049	0.9	1.9	3.71	2.41	2.41	31			168	106	10	1	3	2	3
4.5	84809	Pelican Bay Golf	2.84	1,291	1,291	1.6	2.1	5.21	2.61	2.61	1,291				18	72	1	3	3	1
5.1	76179	Pelican Bay Community Center	1.25	1,127	1,127	1.0	1.6	4.31	2.61	2.61					200	6	1	3	3	2
5.13	94869	Bay Colony Shores	2.18	2,110	2,110	1.4	2.2	3.81	4.01	4.01	232				9	234	0	3	3	3
2.4	80236	Georgetown	1.85	1,918	1,845	1.9	2.2	3.81	2.51	2.51	372	53			14	133	0	3	3	3
4.6	29239	Pelican Bay Golf	0.66	720	673	1.4	1.6	5.11	2.61	2.61	27				26	26	0	3	3	1
4.4	26718	Pelican Bay Golf	0.61	856	695	1.2	2.0	5.41	4.61	4.61	188	161			14	90	0	3	3	2
4.2	67996	Edgewood Park	1.26	1,193	792	1.4	1.8	4.91	4.01	4.01	470	428			16	48	1	3	3	1
2.2	44409	Edgewood Park	1.02	888	316	1.8	2.2	3.91	2.91	2.91	372				1	216	1	3	2	2
2.6	145130	Pelican Bay Golf	3.40	3,245	2,124	1.4	1.8	9.01	5.01	5.01	191				90	24	1	3	3	1
3.5	72296	Pelican Bay Golf	1.66	1,275	1,128	1.2	1.8	7.51	3.51	3.51	463	247			20	56	1	3	3	3
2.12	52270	Pelican Bay Golf	1.20	1,625	1,279	1.3	1.8	11.21	4.61	4.61	346				45	29	0	3	3	1
5.12	194119	Bay Colony Shores	4.46	2,465	1,292	1.2	1.8	3.81	3.11	3.11	1,271	1,079			10	133	0	3	3	4
5.11	82279	Pelican Bay Golf	1.90	1,401	1,401	1.2	1.7	6.21	2.91	2.91	114				12	137	0	3	3	2
4.8	105605	Pelican Bay Golf	2.42	1,877	1,517	1.4	2.8	4.21	2.91	2.91	407	360			1	1,337	0	3	1	4.1
5.14	45203	Bay Colony Shores	1.03	923	923	1.4	1.7	6.41	4.41	4.41	139				7	140	0	3	3	1
5.9	47465	Bay Colony Shores	1.29	956	956	1.2	1.5	6.91	4.71	4.71	435				3	139	1	3	3	2
2.1	28361	Pelican Bay Woods	0.46	821	286	0.6	1.2	9.21	4.41	4.41		435			8	133	0	3	3	1
1.5	194442	Bridge Way / Terra Mar	0.45	770	0	0.7	0.7	5.21	2.71	2.71	0		1,123		14	0	1	2	2	4
6.1	73117	Terrace	1.45	1,448	0	0.0	0.0	-	-	-	1,220			428	47	0	1	3	3	5
1.4	132794	Bridge Way / Terra Mar	0.29	614	0	0.0	0.0	3.11	3.11	3.11		1,402			11	0	0	2	3	4
6.2	31277	Birch-Cedar Hill	0.72	1,402	0	0.0	0.0	-	-	-		1,402			420	0	0	3	3	5

Thomas Jefferson Ct



24" Stormwater RCP
Evaluate/Repair 2020



01/2020
Inspection
Shenandoah

Inspection Report / Inspection 1									
Site Name	City	County	Project Name	Inspector	Inspector's License No.	Inspector's License State	Inspector's License Expiration	Inspector's License Category	Inspector's License Status
Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah
Site No.	Site Name	City	County	Project Name	Inspector	Inspector's License No.	Inspector's License State	Inspector's License Expiration	Inspector's License Category
1000	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah
Site No.	Site Name	City	County	Project Name	Inspector	Inspector's License No.	Inspector's License State	Inspector's License Expiration	Inspector's License Category
1000	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah
Site No.	Site Name	City	County	Project Name	Inspector	Inspector's License No.	Inspector's License State	Inspector's License Expiration	Inspector's License Category
1000	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah	Shenandoah

LINE	Profile	Code	Observation	MPCE	Photo	Grade
1.00	1.00	AB01	Upper's Marked Survey Spot #1	00.00 00		
1.00	1.00	F0	Problem: Construction of Box 10 is 10' above, which is above the ground surface.	00.00 17		
10.00	10.00	10	Setback Distance is 10' above the ground surface.	00.00 13		
10.00	10.00	AB01	Construction Marked Survey Spot #1	00.00 18		

Please See Section 1000, Section 1000, Section 1000, Section 1000, Section 1000, Section 1000, Section 1000, Section 1000, Section 1000, Section 1000

Shenandoah Construction
1888 NW 22nd Street
Pompano Beach FL 33069
954-975-0098
help@shenandoahconstruction.com
shenandoahconstruction.com



Bid award for repairs:
Quality Enterprises

02/2020



02/2020





Damaged 24' stormwater pipe



02/2020



02/2020



Job complete 02/2020

