May 20, 2015 Rock Road MSTU Maintenance

Yellow shows the areas we did last year.

Purple shows the areas done by property owners.

Green shows the areas we did this year

No Color shows the areas that need to be done but not as critical as the ones in green.

Evaluation

- 1. Cypress East Needs Gravel and Grading 0 Loads
- 2. Cypress West Gravel and Grading FY15)
- 3. Deer Run East Needs Gravel and Grading 2 Loads
- Deer Run West Needs Gravel and Grading 2 Loads Per Doug Allemong base rock and grading done by property owners in Dec 2013
- 5. Catawaba middle section Needs Grading Some gravel 0 Loads Not in bad shape but needs some work
- 6. Mingo Drive East Gravel and grading 2013 1 Loads Road is in good shape. Shows almost no wear in the last year.
- 7. Mingo Drive West Gravel and graded FY15. 2 Loads
- 8. Keri Island East Needs Gravel and grading 2014 2 Loads
- 9. Keri Island First West Graded and Gravel FY 15) 2 Loads 1 load added in Aug 2014. This and #10 second worst condition
- 10. Keri Island Second West Graded and Gravel FY 15 2 loads Second worst road.
- 11. Catawaba South Section Gravel and Graded by owners 2014 0 loads Regularly maintained by owners.
- 12. Shady Lane East Needs Gravel and Grading 2 Loads Short road, probably less needed
- 13. Shady Lane West Needs Gravel and Grading 2 Loads Short Road, probably less needed
- 14. Rock Road N-S 1 Gravel and Grading 2013 and Aug 2014 #14-#17 18 loads done in Aug
- 15. Rock Road N-S 2 Gravel and Grading 2013 and Aug 2014 "
- 16. Rock Road N-S 3 Gravel and Grading 2013 and Aug 2014 "
- 17. Rock Road N-S 4 Gravel and Grading 2013 and Aug 2014 "
- 18. Rock Road N-S 5 Gravel and Grading 2013 One bad section. Needs grading with existing gravel