McGee & Associates

Landscape	Architecture
-----------	--------------

Project:	GOLDEN GATE BEAUTIFICATION, M.S.T.U.	Location:	Collier Blvd. Part A & B	
Project Manager:	Harry Sells, MSTU Project Manager, C.C.P.S.D. – P.T.N.E. Dept.			
Consultant:	McGee & Associates	Consultant's Representative:	Michael A. McGee, rla, isa	
Contractor:	Hannula Landscaping & Irrigation Inc.	Contractor's Representative:	Dale Hannula	
Report Period:	FY 14-15, June 2015	Report No.:	Nine – FY 14-15	
<u>S</u> - Indicates items	to be addressed by staff.	<u>C</u> - Indicates items to be addressed by Contractor		
This was and is more a	and stated to the many data as a second state and the second terms are the second state as a second state of the	- include a second s	we also and the Orale Oraction at a set	

This report is prepared strictly to provide recommendations only and in no manner is to imply any authorization to the Contractor or its Sub-Contractors to perform services for Collier County. Contractor is requested to address items as soon as possible and indicate in <u>RESPONSE/COMMENTS</u> column when and which items are corrected. Please return electronic copy to our office prior to next month's MSTU site review and meeting.

Note: Copy picture out of comment boxes and then paste to additional sheet if picture is desired in larger size.

LOCATION/WORK AREA	<u>S</u>	<u>C</u>	<u>R</u>	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
Observation dates: 06/08-11/15				MONTHLY ADDRESSED	
Median# 8 - 12					
Part "A" - West R/W Sign Area		Х	15	Recommend removing Crown of thorn and mulch area.	
Median #3		Х	8	Recommend removing Thryallis shrubs and install Sand Cordgrass.	
Median #4		X	8	Recommend removing two remaining beds of Red Fountain grass and replant areas with Silver Saw palmetto's.	
Median #5		Χ		Review and treat Big Rose Crown of thorn for snails. Review for replacement plantings.	
		Х	13	Prune back the deadwood within the Magnolia at the northernmost end.	
Median #6 – Paved separator					
Part "B" - Median #7		X	13	Juniper bed on south end of median contains dead plants and brown foliage. Remove both and provide count for replacements.	
Median #8		X	13	Juniper bed on south end of median contains dead plants and brown foliage. Remove both and provide count for replacements.	
		X	17	Plant replacements are needed in multiple areas.	Hannula 12/20/13: An estimate cannot be submitted without knowing the recommended species for replacement and a plant count. M&A 1-15-14: Please call our office to schedule an on-site meeting to review median.
Median #9		Х	23	Review Juniper on north and south end for replacements due to auto damaged.	Hannula 12/20/13: Plant count is needed by next drive through
Median #10		Χ	18	Review south end Juniper bed for replacements.	
		Х	17	Turf areas need to be reviewed for dead areas that need to be replaced.	Provide proposal with square footages per median.
Median #11		Х	13	Remove dead Indian hawthorn plants and replace. (8) 3 gal. size.	

Design * Environmental Management * Planning * Arborist

5079 Tamiami Trail East / P. O. Box 8052 Naples, Florida 34101 Phone (239) 417-0707 * Fax (239) 417-0708 LC 098 * FL 1023A


McGee & Associates

Landscape Architecture

LOCATION/WORK AREA	<u>S</u>	<u>C</u>	<u>R</u>	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
		Χ	16	Turf areas need to be reviewed for dead areas that need to be replaced.	Provide proposal with square footages per median.
West R/W					
Irrigation:	X	X	7	The water use for December was extremely high for Part A and a little high for Part B considering the medians have been reduced in numbers. Review system and controller for issues. If the Bermad pulse counters are working, then request from the County Irrigation Project Manager to set the maximum flow per week at 25,000 gallons for Part A and 55,000 gallons for Part B at which time an alarm will be sent to Hannula Landscaping.	M&A: 4/15/15 Please update status.
Part A Pump Station- Median #4, 5 hp , 6" well, VFD	X	X	11	It is recommended to replace existing Bermad Hydro-meter with an upgraded model. The existing Bermad flow meter readings are becoming unreadable do to the frosting of the plastic cover.	
Motorola Scorpio controller S3406					
Electric meter on west R/W at pump station, G Irrigation 951A					
Part B Pump Station-Median #11, 7.5 hp , 6" well, VFD					
Electric Meter West R/W adjacent to Median #9 Address 12225					
Motorola Scorpio controller S3405 & S3408					
				QUARTERLY ADDRESSED	
Part "A" - West R/W Sign Area					
Part "A" Medians #3 thru 5	x	x	18	These medians need to have renovation plantings. The future roadway construction appears to be more than10 years out.	Hannula 12/20/13: An estimate cannot be submitted without knowing the recommended species for replacement and a plant count Area(s) must be white lined during drive-through upon acceptance of estimate. M&A 1-15-14: Please call our office to schedule an on-site meeting to review medians
Part "B" - West R/W Areas		Х		Review all canopy type tree locations adjacent to the sidewalks for the canopies being less than ten feet above the sidewalk.	
Part "B" Medians #7 thru 11					
18th Ave. S.W. Median					

McGee & Associates

Landscape Architecture



Water Use Goal:

(Original Part A =1.63 ac. of plants, Part B = 2.74 ac. of plants and turf, Revised Part B = 1.86, New Total Irrigated Area = 3.49 ac.)

Recommended: Supplemental watering rate of .5 to .75 inch per week.

Three-quarter inch per week equals 71,076 gallons per week or 284,305 gallons per month.

Combined 2012 total water use: 2,222,816 gallons or 18.73 inches of supplemental water pumped.

Combined 2013 total water use: 3,705,865 gallons or 31.23 inches of supplemental water pumped.

2014 Part B well & pump station relocated on 7/24/14. New well active 09/2014

Combined 2014 total water use: 3,147,554 gallons or 26.26 inches of supplemental water pumped.