

Project: GOLDEN GATE BEAUTIFICATION, M.S.T.U. Location: Collier Blvd. Part A & B

Project Manager: Darryl Richards, r.l.a., P.S.D. – P.T.N.E. Dept.

Consultant: McGee & Associates Consultant's Representative: Michael A. McGee, rla, isa

Contractor: Hannula Landscaping & Irrigation Inc.

Report Period: FY 14-15, January 2015

Report No.: Four – FY 14-15

Contractor's Representative: Dale Hannula

Report No.: Four – FY 14-15

<u>S</u> - Indicates items to be addressed by staff.

This report is prepared strictly to provide recommendations only and in no manner is to imply any authorization to the Contractor or its Sub-Contractors to perform services for Collier County. Contractor is requested to address items as soon as possible and indicate in **RESPONSE/COMMENTS** column when and which items are corrected.

Please return electronic copy to our office prior to next month's MSTU site review and meeting.

Note: Copy picture out of comment boxes and then paste to additional sheet if picture is desired in larger size.

LOCATION/WORK AREA	<u>s</u>	<u>C</u>	<u>R</u>	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
Observation dates: 01/12-15/15				MONTHLY ADDRESSED	
Median# 8 - 12					
Part "A" - West R/W Sign Area		X	10	Recommend removing Crown of thorn and mulch area.	
Median #3		Х	2	Clean mulch out of curbing on north end of median.	
		X	3	Recommend removing Thryallis shrubs and install Sand Cordgrass.	
Median #4		X	2	Clean mulch out of curbing on south end of median.	
		X	3	Recommend removing two remaining beds of Red Fountain grass and replant areas with Silver Saw palmetto's.	
Median #5		Х	8	Prune back the deadwood within the Magnolia at the northernmost end.	
Median #6 - Paved separator					
Part "B" - Median #7		Х	8	Juniper bed on south end of median contains dead plants and brown foliage. Remove both and provide count for replacements.	
Median #8		Х	8	Juniper bed on south end of median contains dead plants and brown foliage. Remove both and provide count for replacements.	
		Х	12	Plant replacements are needed in multiple areas.	Hannula 12/20/13: An estimate cannot be submitted without knowing the recommended species for replacement and a plant count. M&A 1-15-14: Please call our office to schedule an on-site meeting to review median.
Median #9		Х	18	Review Juniper on south end for replacements due to auto damaged.	Hannula 12/20/13: Plant count is needed by next drive through
Median #10		X	13	Review south end Juniper bed for replacements.	
		Х	12	Turf areas need to be reviewed for dead areas that need to be replaced.	Provide proposal with square footages per median.

Design * Environmental Management * Planning * Arborist



GOLDEN GATE BEAUTIFICATION, M.S.T.U. Location: Collier Blvd. A & B Report Period: FY14-15, January 2015 Report No.: Four

LOCATION/WORK AREA	<u>S</u>	,		MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
	<u> 2</u>				INLEST ON SELECTION OF CONTINUE IN 13
Median #11		Х		Remove dead Indian hawthorn plants and replace. (8) 3 gal. size.	
		Х	11	Turf areas need to be reviewed for dead areas that need to be replaced.	Provide proposal with square footages per median.
Median #12		X		West side turf area has large dry areas.	
		X	11	Turf areas need to be reviewed for dead areas that need to be replaced.	Provide proposal with square footages per median.
Median #13		X		Median to be abandoned due to future roadway improvements.	
Median #14		Х		Median to be abandoned due to future roadway improvements.	
Median #15		Х		Median to be abandoned due to future roadway improvements.	
West R/W					
Green Blvd Median #1		X		Median abandoned due to future roadway improvements.	
18th Ave. S.W. Median		Х	9	Auto accident has removed 6 to 8 Bougainvillea plants on northwest side. Review and provide count for replacements.	
Irrigation:	X	X	2	The water use for December was extremely high for Part A and a little high for Part B considering the medians have been reduced in numbers. Review system and controller for issues. If the Bermad pulse counters are working, then request from the County Irrigation Project Manager to set the maximum flow per week at 25,000 gallons for Part A and 55,000 gallons for Part B at which time an alarm will be sent to Hannula Landscaping.	
		X		The irrigation water use is extremely high for Part B and high for Part A. For Part A based upon the 1.63 ac. of irrigated area; (1 acre inch of water equals 27,154.29 gallons) the water use of 161,930 gallons applied 3.6 inches of water over one month. Please review the system for leaks and the flow meter accuracy. Please review the system for leaks and the flow meter accuracy. For Part B based upon the 2.74 ac. of irrigated area; (1 acre inch of water equals 27,154.29 gallons) the water use of 465,856 gallons applied 6 inches of water over one month. By copy of this report we recommending that the system have a maximum amount flow alarm or shut down entered into the system. Recommended maximum flow for Part A south of G.G. Parkway should be set at 80,000 gallons. Recommended maximum flow for Part B north of G.G. Parkway: Once new well and pump station are operational flow demand will need to be reevaluated to determine flows. It is also recommended to perform a main line leak test. The test is to consist of pressurizing the main line for a 24 hour period and to take flow meter readings before and after.	M&A: 7/9/14 Irrigation system is being evaluated by contractor and consultant. M&A: 11-13-14 Once existing Bermad pulse counters are working it is recommended to set a weekly high use alarm for the systems as listed below. Part B irrigated area is now 1.86 ac. Pump station Part A - 25,000 gallons. Pump station Part B - 55,000 gallons.
Part A Pump Station- Median #4, 5	X	X	6	It is recommended to replace existing Bermad Hydro-meter with an upgraded model. The	
hp , 6" well, VFD				existing Bermad flow meter readings are becoming unreadable do to the frosting of the plastic cover.	
Motorola Scorpio controller S3406	\vdash			plastic cover.	
Electric meter on west R/W at					
pump station, G Irrigation 951A					
Part B Pump Station-Median #11,					



GOLDEN GATE BEAUTIFICATION, M.S.T.U. Location: Collier Blvd. A & B Report Period: FY14-15, January 2015 Report No.: Four

				•	
LOCATION/WORK AREA	<u>S</u>	<u>C</u>	<u>R</u>	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
7.5 hp , 6" well, VFD					
Electric Meter West R/W adjacent					
to Median #9 Address 12225					
Motorola Scorpio controller S3405					
& S3408					
				QUARTERLY ADDRESSED	
All Shrub plantings					
Part "A" - West R/W Sign Area					
Part "A" Medians #3 thru 5	Х	Х	13	These medians need to have renovation plantings. The future roadway construction appears to be more than 10 years out.	Hannula 12/20/13: An estimate cannot be submitted without knowing the recommended species for replacement and a plant count Area(s) must be white lined during drive-through upon acceptance of estimate. M&A 1-15-14: Please call our office to schedule an on-site meeting to review medians.
Part "B" Medians #7 thru 12					
18th Ave. S.W. Median					



GOLDEN GATE BEAUTIFICATION, M.S.T.U.

Location: Collier Blvd. A & B

Report Period: FY14-15, January 2015 Report No.: Four


LOCATION/WORK AREA

<u>S</u> <u>C</u>

MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS

RESPONSE or COMMENTS

GG MSTU Collier Blvd. Part A & B, Well Annual Water Use for 2014



Water Use Goal:

(Original Part A = 1.63 ac. of plants, Part B = 2.74 ac. of plants and turf, Revised Part B = 1.86, New Total Irrigated Area = 3.49 ac.)

Recommended: Supplemental watering rate of .5 to .75 inch per week.

Three-quarter inch per week equals 71,076 gallons per week or 284,305 gallons per month.

Combined 2012 total water use: 2,222,816 gallons or 18.73 inches of supplemental water pumped.

Combined 2013 total water use: 3,705,865 gallons or 31.23 inches of supplemental water pumped.

2014 Part B well & pump station relocated on 7/24/14. New well active 09/2014

Combined 2014 total water use: 3,147,554 gallons or 26.26 inches of supplemental water pumped.

1/02/2015