

McGee & Associates

Landscape Architecture

Project: GOLDEN GATE BEAUTIFICATION, M.S.T.U.
Project Manager: Leslie Hayes, MSTU Project Manager, C.C.P.S.D. – P.T.N.E. Dept.
Consultant: McGee & Associates
Contractor: Hannula Landscaping & Irrigation Inc.
Report Period: FY 15-16, November 2015

Location: Golden Gate Pkwy.
Consultant's Representative: Michael A. McGee, rla, isa
Contractor's Representative: Dale Hannula
Report No.: Two

S - Indicates items to be coordinated by administrative and/or maintaining department staff. **C** - Indicates items to be addressed and/or brought to the attention of maintaining staff by Contractor

<u>MAINTENANCE ITEM</u> Observation date: 11/09-12/15	<u>S</u>	<u>C</u>	<u>R</u>	<u>SUMMARY OF MONTHLY</u> MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	<u>RESPONSE or COMMENTS</u> Refer to monthly report for detailed information.
TRESS	X	X	3	Schedule annual Sabal /Cabbage palm pruning lower fronds and seed stalks.	
	X	X		Multiple Oak trees and one Poinciana trees have canopies that are less than 15 feet and/or encroaching into the travel or turn lanes. Minor canopy pruning is recommended.	See monthly report "Quarterly Addressed" items for detailed locations.
SHRUBS & ORNAMENTAL GRASSES	X	X		Shrubs and ground covers have been damaged in median #19 due to Mast Arm Traffic signal installation.	
		X	3	Review shrub and grass beds for replacements.	Turf renovation plan will address plant replacements. Turf renovation plan completed and submitted.
GROUND COVERS		X	3	Blueberry Flax lily and Liriope beds throughout the medians contain excess amounts of Torpedo grass weeds. recommend ongoing program of hand removal and/or treatment until removed.	
		X	3	It is recommended the west entry community sign be planted with plants as follows: Starting in front of the light fixture plant three (3) staggered rows, 4' o.c. of 3 gal. size dwarf Bougainvillea 'Helen Johnson" for a total of 21 plants, then in front of Bougainvillea install 262 perennial peanut in 1 gal. size 1 ft. o.c.	
TURF	X	X	3	All median with turf have excess amounts of broadleaf and grass type weeds.	
IRRIGATION		X		Pump station water use meters are showing readings.	
	X	X		Irrigation system damaged in median #19 due to Mast Arm Traffic signal installation.	
WEED CONTROL		X	3	Turf weeds and Torpedo grass weed in excessive amounts throughout medians.	
UNDERSTORY PRUNING		X	3	Ornamental grass (e.g. White & Red Fountain grass) needs to be reviewed for pruning.	
DISEASE AND PEST CONTROL		X		No observed issues.	
FERTILIZATION		X		No observed deficiencies.	
HARDSCAPE ELEMENTS	X	X	3	The Advisory Committee installed Mr. Farrow and Mr. Melchore memorial plaque and base need to be cleaned, repainted and the pavers repaired so that memorial is secure.	

Design * Environmental Management * Planning * Arborist

5079 Tamiami Trail East / P. O. Box 8052 Naples, Florida 34101
 Phone (239) 417-0707 * Fax (239) 417-0708
 LC 098 * FL 1023A