

# *McGee & Associates*

Landscape Architecture

**Project:** GOLDEN GATE BEAUTIFICATION, M.S.T.U.      **Location:** Coronado Pkwy. and Hunter Blvd.  
**Project Manager:** Collier County Public Services Division, Public Transportation & Neighborhood Enhancements Department.  
**Consultant:** McGee & Associates      **Consultant's Representative:** Michael A. McGee, rla, isa  
**Contractor:** Hannula Landscaping & Irrigation Inc.      **Contractor's Representative:** Dale Hannula  
**Report Period:** FY 16-17, February 2017      **Report No.:** Five

**AC** - Indicates major items recommended to be discussed by Advisory Committee, **S** - Indicates items recommended to be addressed by staff,

**C** - Indicates items recommended to be addressed by Contractor

| <b>MAINTENANCE ITEM</b><br>Observation date: 2/10-14/16   | <b>AC</b> | <b>S</b> | <b>C</b> | <b>R</b> | <b>SUMMARY OF MONTHLY<br/>MAINTENANCE SERVICES OBSERVATIONS &amp; RECOMMENDATIONS</b>  | <b>RESPONSE or COMMENTS</b><br>Refer to monthly report for detailed information                   |
|---|-----------|----------|----------|----------|--|---|
| <b>TREES</b>  |           |          | X        | 2        | Hunter Blvd. Med. #10: 1 Alexander palm and 14 Big rose damaged due to auto accident.  |   |
|   |           |          | X        | 3        | Hunter Blvd. median #11: Silk floss tree removed due to auto accident. (photo)   |   |
|   |           |          | X        | 5        | Auto accident damage in Hunter Blvd. median #1. A proposal for replacements has been requested. Alexander palm & Juniper damaged.  |   |
| <b>SHRUBS, ORNAMENTAL GRASSES<br/>&amp; GROUND COVERS</b> |           |          | X        | 15       | Review beds for replacements. A comprehensive project length estimate should be developed.   | Estimate #15-3309 12/15/15 submitted and under review. M&A: 2/14/17 New proposal being generated. |
| <b>IRRIGATION</b>   |           |          | X        |          | January water use meter readings indicate 62,422 gallons used for both roadways.   |   |
| <b>WEED CONTROL</b>                                       |           |          | X        |          | No major issues observed   |   |
| <b>UNDERSTORY PRUNNING</b>                                |           |          | X        |          | No major issues observed   |   |
| <b>DISEASE AND PEST CONTROL</b>                           |           |          | X        |          | No major issues observe with regards to pest control, but a comprehensive review is needed to determine what is causing the overall decline and death of the flax lily plantings. Soil and plant analysis are recommended, along with no more spraying of herbicide around any Flax lily plants and the pull back of mulch away from the plant bases and any mulch piled within the plants themselves. |   |
| <b>FERTILIZATION</b>                                      |           |          | X        |          | Review FY16-17 schedule.   |   |

Commented [M&A1]:



**Design \* Environmental Management \* Planning \* Arborist**

5079 Tamiami Trail East / P. O. Box 8052 Naples, Florida 34101  
 Phone (239) 417-0707 \* Fax (239) 417-0708  
 LC 098 \* FL 1023A