

GOLDEN GATE BEAUTIFICATION M.S.T.U.

**8300 Radio Road
Naples, FL 34104**

AGENDA **JANUARY 19, 2021**

I. CALL TO ORDER

II. ATTENDANCE

Advisory Committee Patricia Spencer – Chair (10/06/2021)
Paula Rogan – Vice Chair (10/06/2023)
Florence “Dusty” Holmes (10/06/2021)
Ron Jefferson (10/06/2022)
- Vacancy -

Staff Michelle Arnold – PTNE Director
Dan Schumacher, Harry Sells – Project Managers

Contractors Mike McGee – Landscape Architect (McGee & Assoc)
Mike Patterson – Grounds Maintenance (Mainscape)

III. PLEDGE OF ALLEGIANCE

IV. APPROVAL OF AGENDA

V. APPROVAL OF MINUTES [NOVEMBER 17, 2020](#)

VI. LANDSCAPE MAINTENANCE REPORT – MAINSCAPE

VII. LANDSCAPE ARCHITECT’S REPORTS – MCGEE & ASSOCIATES

- A. [Tropicana](#) Boulevard**
- B. [Sunshine](#) Boulevard**
- C. [Coronado](#) Parkway & [Hunter](#) Boulevard**

VIII. PROJECT MANAGER’S REPORT

- A. Election of Officers – February 2021.**
- B. Budget [Report](#).**
- C. Complete Streets Report – Johnson Engineering – Present in February?**
- D. Median Refurbishment – Plant Replacements.**
- E. Pkwy Bridge Replacement – Transportation Engineering – Present in March?**
- F. FPL – Leaning Poles.**

IX. OLD BUSINESS

X. NEW BUSINESS

XI. PUBLIC COMMENTS

XII. ADJOURNMENT

**NEXT MEETING:
FEBRUARY 16, 2021 AT 4:30 PM
GOLDEN GATE COMMUNITY CENTER
4701 GOLDEN GATE PARKWAY
NAPLES, FL 34116**



GOLDEN GATE M.S.T.U. ADVISORY COMMITTEE

**8300 Radio Road
Naples, FL 34104**

NOVEMBER 17, 2020

MINUTES

I. Call to Order

The meeting was called to order at 4:30 P.M. by Chair Spencer. Attendance was called and a quorum of three was present.

II. Attendance

Advisory Committee	Patricia Spencer – Chair Paula Rogan Florence “Dusty” Holmes (Excused) Ron Jefferson Vacancy
Staff	Michelle Arnold – PTNE Director (Excused) Dan Schumacher, Collier County – Project Manager Rosio Garcia, Collier County – Administrative Assistant (Excused)
Landscape	Mike McGee – Landscape Architect (McGee & Assoc) Mike Patterson – Grounds Maintenance (Mainscape) (Excused)
Other	Wendy Warren, Premier Staffing – Transcriptionist

III. Pledge of Allegiance

The Pledge of Allegiance was recited.

IV. Approval of Agenda

*Chair Spencer moved to approve the Agenda of the Golden Gate Advisory Committee as presented.
Second by Ms. Rogan. Carried unanimously 3 - 0.*

V. Approval of Minutes October 20, 2020

*Chair Spencer moved to approve the minutes of the October 20, 2020 meeting as presented.
Second by Ms. Rogan. Carried unanimously 3 - 0.*

MINUTES

VI. Landscape Maintenance Report – Mainscape Landscaping Company

Addressed in the landscape Architect's report.

VII. Landscape Architect's Report – McGee & Associates

Mr. McGee reported:

- Medians have been cleaned; weeds are under control.
- A spread sheet will be created detailing landscape replacements for all roadways to enable Mainscape Landscaping to provide quotes for median refurbishment.
- A list of ornamental trees requiring structural pruning and lifting of canopies will be provided to Staff.

A. Tropicana Boulevard

Median #1

- Remove all Bougainvillea back to existing Juniper and install Dwarf Asian Jasmine from north end to existing Junipers. Install (9) ten-inch (10") pot Acehmea Blanchetiana "Raspberry" Bromelaid between Oak trees and Sabal palms.

Median # 3 Bridge

- Remove north side Flax Lily and replant with approximately thirty-six (36) Yellow African Iris one (1) gallon size.

B. Sunshine Boulevard

18th Ave. S.W. Median:

- Prune Sabal palms
- Replant Sabal palm by Collier Boulevard
- Replant Perennial Peanut damaged by herbicide application. Mainscape to provide count for one (1) gallon 'Ecoturf' planting.

C. Coronado Parkway & Hunter Boulevard

Median #4

- Replace four (4) Alexander palms damaged by an auto accident.

Irrigation

- Wet checks are done bi-weekly.
- Irrigation heads should be flush with ground level.

Water Usage

November 2020's water use total per WeatherTrak controller estimates:

- Tropicana Boulevard – 108,837 gallons.
- Sunshine Boulevard – 160-209 gallons.
- Coronado Pkwy & Hunter Boulevard – 83,647 gallons.

Mr. McGee noted:

- Increase in landscape replacements from interruption of routine maintenance service due to resignation of previous contractor and excessive weed growth.
- Mulch should be applied to medians.
- Irrigation is adequate for median landscape renovation.

Mr. Schumacher will contact Hart's Electrical to check-out light poles on Tropicana median #6 illuminated during daytime.

MINUTES

VIII. Project Manager's Report

A. Budget Report

Mr. Schumacher summarized the “*Golden Gate MSTU Fund Budget 153 dated November 17, 2020*” for information purposes and provided an overview of the budget noting:

- FY21 Ad Valorem property tax revenue budget is \$493,900.00, an increase of 11.44% over FY20.
- Total revenue FY21 is \$1,304,234.75 including investment interest, transfers, and contributions.
- The FY-21 Millage rate remains constant at 0.5000%.
- Current Operating Expense Budget is \$330,834.75 of which Commitments total \$179,530.14; Expenditures \$13,319.61.
- Uncommitted Operating Expense funds available are \$137,985.00.
- The Landscape Ground Maintenance Purchase Order is for routine monthly maintenance; Landscape Incidentals PO covers plant refurbishment.
- McGee & Associates 2021 contract for Landscape Architectural Services in the amount of \$23,290.00 is recorded on line17.
- Florida Power & Light expense funds electricity for lights and pumps.
- Forestry Resources, operating under a County Contract, will supply mulch for application upon completion of median refurbishment.
- HydroPoint's annual subscription for a suite of ongoing performance management tools will be paid at a later date.
- SiteOne supplies parts for the irrigation system.
- The FY-20 Purchase Order balance for Premier Staffing in the amount of \$1,534.75, available for outstanding 2020 invoice submissions, will be closed out.
- Fertilizer purchased from Howard Fertilizer will be delivered to Mainscape to be applied to medians.
- Transfer to 111, Line 37, is reimbursement for Staff salaries.
- Improvements General Fund, Line 35, reserved to fund capital projects or multi-year landscape contract deficit, available balance is \$905,000.00.
- Budget Transfers Appraiser and Tax Collector, Lines 38 and 39, are fees billed by the appropriate entities.
- Total available balance, less committed expenses, is \$1,110,392.46.

B. Bridge Painting

Mr. Schumacher reported project status is unchanged and the Committee will be updated at a future meeting.

C. Ornamental Pruning & Plant Replacement

Mr. McGee discussed this topic during his Landscape Summary Report dated 11.2.2020 (Item VII).

D. Parkway Bridge Replacement

Mr. Schumacher attended a meeting of the “Complete Streets” work group in February 2020. Policy and plans related to providing a safe and comprehensive bicycle and pedestrian network encouraging community use and enjoyment were discussed; including traffic roundabouts, bike lanes, and pedestrian walkways (sidewalks) on Golden Gate Pkwy.

MINUTES

Pages from Concept Plans dated June 2020 for the new bridge and a project release document dated November 2020, both issued by the Growth Management Department, were distributed to the committee.

- The Santa Barbara canal bridge on Golden Gate is to be replaced.
- Three existing bridges will be replaced with a single span that includes two travel lanes, a shoulder, and a sidewalk in each direction.
- Landscaping is expected in the thirteen-foot (13) median.
- Construction is scheduled to commence and be completed in 2022.
- The work will take place in two (2) phases to maintain travel on the bridge.

Mr. Schumacher will:

- Invite a project representative to address the MSTU Committee.
- Confirm the availability of irrigation in the vicinity.
- Investigate plans for the pedestrian bridges that will be removed for reuse within the MSTU boundaries.

IX. Old Business

None

X. New Business

None

XI. Public and Board Comments

Mr. Jefferson reported news coverage of development of the Golden Gate Country Club 167-acre golf course by the County revealed some residents were not aware of the project.

XII. Adjournment

There being no further business to come before the Committee, the meeting was adjourned by the Chair at 5:10 P.M.

GOLDEN GATE MSTU ADVISORY COMMITTEE

Patricia Spencer, Chair

The Minutes were approved by the Committee on _____, 2020 as presented _____, or as amended _____.

**NEXT MEETING:
DECEMBER 15, 2020 – 4:30 PM
GOLDEN GATE COMMUNITY CENTER
4701 GOLDEN GATE PARKWAY
NAPLES, FL 34116**

**Golden Gate MSTU
FY21
January 19, 2021**

	FY-21	Vendor	Item	PO#	Budget	Commitments	Expenditures	Budget Remainder
1	CUR AD VALOREM TAX				\$ (493,900.00)	\$ -	\$ (411,537.25)	\$ (82,362.75)
2	DEL AD VALOREM				\$ -	\$ -	\$ (26.32)	\$ 26.32
3	OVERNIGHT INTEREST				\$ -	\$ -	\$ (439.43)	\$ 439.43
4	INVESTMENT INTEREST				\$ (8,000.00)	\$ -	\$ (1,339.08)	\$ (6,660.92)
5	REVENUE STRUCTURE				\$ (501,900.00)	\$ -	\$ (413,342.08)	\$ (88,557.92)
6	TRANS FROM PROPERTY APPRAISER				\$ -	\$ -	\$ -	\$ -
7	TRANS FROM TAX COLLECTOR				\$ -	\$ -	\$ -	\$ -
8	CARRY FORWARD GEN				\$ (825,900.00)	\$ -	\$ -	\$ (825,900.00)
9	CARRY FORWARD OF ENCUMB				\$ (1,534.75)	\$ -	\$ -	\$ (1,534.75)
10	NEG 5% EST REV				\$ 25,100.00	\$ -	\$ -	\$ 25,100.00
11	TRANSFERS & CONTRIB				\$ (802,334.75)	\$ -	\$ -	\$ (802,334.75)
12	TOTAL REVENUE				\$ (1,304,234.75)	\$ -	\$ (413,342.08)	\$ (890,892.67)
13	ENG. FEES & OTHERS	McGee & Associates	Landscape Architect	4500207529	\$ 40,000.00	\$ 20,125.30	\$ 3,164.70	\$ 16,710.00
14	INDIRECT COST REIMBURSE	Collier County	Indirect Cost	Direct Pay	\$ 7,000.00	\$ 3,500.00	\$ 3,500.00	\$ -
15	LANDSCAPE INCIDENTALS	Mainscape	Landscape Incidentals	4500206700	\$ 30,000.00	\$ 30,000.00	\$ -	\$ -
16	OTHER CONTRACTUAL	Mainscape	Grounds Maintenance	4500206700	\$ 200,000.00	\$ 107,251.60	\$ 12,748.40	\$ 80,000.00
17	ELECTRICITY	FPL	Electricity	4700004404	\$ 3,500.00	\$ 2,200.91	\$ 574.09	\$ 725.00
18	RENT EQUIPMENT				\$ 300.00	\$ -	\$ -	\$ 300.00
19	INSURANCE GENERAL	Collier County	Insurance General	Direct Pay	\$ 700.00	\$ 525.00	\$ 175.00	\$ -
20	SPRINKLER SYSTEM	SiteOne	Pumps & related items	4500207010	\$ 10,000.00	\$ 2,177.45	\$ 322.55	\$ 7,500.00
21	MULCH				\$ 12,000.00	\$ -	\$ -	\$ 12,000.00
22	LIGHTING MAINTENANCE	Hart's Electrical	Lighting Maintenance	TBD	\$ 12,000.00	\$ 1,846.99	\$ 153.01	\$ 10,000.00
23	LICENSE & PERMITS				\$ 4,000.00	\$ -	\$ -	\$ 4,000.00
		Premier Staffing (FY20)	Transcriptionist	4500199301	\$ -	\$ -	\$ -	\$ -
		Premier Staffing (FY21)	Transcriptionist	4500207137	\$ -	\$ 2,459.95	\$ 490.05	\$ -
24	OTHER MISCELLANEOUS				\$ 4,534.75	\$ 2,459.95	\$ 490.05	\$ 1,584.75
25	OFFICE SUPPLIES				\$ 300.00	\$ -	\$ -	\$ 300.00
26	COPYING CHARGES	JM Todd	Copies	4500207221	\$ 300.00	\$ 67.80	\$ 32.20	\$ 200.00
27	FERT HERB CHEM	Howard Fertilizer	Fertilizer	VISA	\$ 5,000.00	\$ -	\$ 1,321.00	\$ 3,679.00
28	OTHER OPERATING				\$ 1,000.00	\$ -	\$ -	\$ 1,000.00
29	OTHER TRAINING				\$ 200.00	\$ -	\$ -	\$ 200.00
30	OPERATING EXPENSE				\$ 330,834.75	\$ 170,155.00	\$ 22,481.00	\$ 138,198.75
31	IMPROVEMENTS GENERAL				\$ 905,000.00	\$ -	\$ -	\$ 905,000.00
32	DATA PROCESSING	Computers at work/Vtechio	Lapt top for Project Mgr.-(Cost Divided by MSTU's)_		\$ -	\$ 700.00	\$ -	\$ (700.00)
33	CAPITAL OUTLAY				\$ 905,000.00	\$ 700.00	\$ -	\$ 904,300.00
34	TRANS FROM 152 FUND TO 111 FUND		Reimbursement for Staff Support		\$ 53,700.00	\$ -	\$ -	\$ 53,700.00
35	TRANS FROM PROPERTY APPRAISER				\$ 4,400.00	\$ -	\$ 1,846.08	\$ 2,553.92
36	TRANS FROM TAX COLLECTOR				\$ 10,300.00	\$ -	\$ 8,481.27	\$ 1,818.73
37	TRANSFERS				\$ 68,400.00	\$ -	\$ 10,327.35	\$ 58,072.65
38	TOTAL BUDGET				\$ 1,304,234.75	\$ 170,855.00	\$ 32,808.35	\$ 1,100,571.40

797,305,507	FY 10 Final Taxable Value	
548,992,684	FY 11 Final Taxable Value	
478,980,702	FY 12 Final Taxable Value	
516,253,177	FY 13 Final Taxable Value	
533,888,677	FY 14 Final Taxable Value	
575,541,732	FY 15 Final Taxable Value	
611,031,317	FY 16 Final Taxable Value	
673,743,701	FY 17 Final Taxable Value	
749,340,700	FY 18 Final Taxable Value	
813,136,298	FY 19 Final Taxable Value	
886,318,740	FY 20 Final Taxable Value	
9.00%	Adjustment FY19 to FY20	
	FY 20	FY 19
Millage	0.5000	0.5000
Extension	443,159	406,568
FY 20 Gross Taxable Value	886,318,740	
Minus: New Const. Annex.	4,123,285	
Plus: Amendment #1 TV Component	0	
Adj. Taxable Value	882,195,455	
Prior year FY19 Levy (Proceeds)	406,568	
Rolled Back Rate (less Amend One)	0.4609	
91% of Rolled Back Rate	0.4194	

0.5 mill cap

Total Available Balance	\$ 1,100,571.40
Plus Committed And Not Spent	\$ 170,855.00
Estimated Cash	\$ 1,271,426.40
Estimated Cash Less Uncollected Ad Valorem Taxes	\$ 1,189,063.65

Prepared 1/14/2021

Project: GOLDEN GATE BEAUTIFICATION, M.S.T.U.

Landscape Architect Report: January 2021

Location: Tropicana Blvd.

Project Manager: Dan Schumacher, Collier County Public Services Department, Public Transportation & Neighborhood Enhancements Division

Consultant: McGee & Associates

Consultant's Representative: Michael A. McGee, rla, isa

Landscape Contractor: Mainscape

Contractor's Representative: Jeff Dulaney

Observation Date: 01/04/2021

Report Date: 01/04/2021

Report No.: 3 (FY-21)


AC - Indicates major items recommended to be discussed by Advisory Committee **S** - Indicates items recommended to be addressed by staff, **C** - Indicates items recommended to be addressed by Contractor

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
					MONTHLY ADDRESSED	Yellow - Items recommended to be addressed as soon as possible or renovation recommendations generally based upon vehicular or storm damage.
All locations:					Roadway replacement & ornamental tree pruning bid schedule being developed for pricing.	M&A: 01/04/21 replacement & pruning bid schedule under review & development.
Median #1	X	X	X	37	All paver areas need to be pressure washed. North half of the median needs renovation plantings.	M&A: Wet and Forget Product maybe tested M&A: 11-3-20 Remove all Bougainvillea back to existing Juniper. Install (475) 1 gal. size Dwarf Asian Jasmine from north end to existing Junipers. Install (9) 10" pot Acehmea blanchetiana "Raspberry" Bromeliad between Oak trees and Sabal palms.
Median #2					No major issue observed.	
Pedestrian shelter at 31st Ave. SW					No major issue observed.	
Median #3 Bridge		X	X	21	Review Blueberry flax lily for insects/snails and/or disease due to the decline of the bed. Remove dead foliage and pull away any mulch in contact with plant bases.	M&A: 6/10/19 Recommend removing north side Flax lily and replant with Yellow African iris 1 gal., Approx. 36 plants 4' o.c., 4' off back of curbing and guard rail
Median #4					No major issue observed.	
Pedestrian Shelter at 28th Ave.SW						
Median #5		X	X	37	At address 2600: Oak 18" caliper, 50% damaged in main trunk from broken off large branch.	Recommend removal and replace. M&A: 7/9/18: Remove Oak tree and grind stump to planting depth and remove debris. Backfill any hole to match existing profile with clean native topsoil (3 c.y. +/-). Install (1) Quercus virginiana 'Cathedral' Live Oak 14'-16' ht., 7'-8' spr, 6"-7" cal., 44" B&B or 100 gal.
		X	X	37	At address 2582: Holly tree has upper trunk damaged. Needs structural and corrective pruning to regrow new main leader.	
		X	X	36	At address 2530: Jacaranda tree needs structural and corrective pruning.	
Median #6					No major issue observed.	
					QUARTERLY ADDRESSED	
Accent/Street Lighting					No major issue observed.	
Lighting Disconnect & Sensor Locations					East R/W between 13th Ave. & PL. Lighting Disconnect & Sensor West Alley off 28 th Ave. SW Lighting Disconnect & Sensor West R/W in Alley between G.G. Pkwy. & 26 th PL. SW, Lighting Disconnect & Sensor West R/W at corner of 30 th PL. SW & Tropicana Lighting Disconnect & Sensor	
Fertilizations:		X	X		Refer to FY-20-21 schedule.	

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
Irrigation:		X			Previous month water use total per WeatherTrak controller estimate 146,562 gallons.	

Collier County
 Site: Golden Gate MTSU
 09012040 - 2001 Tropicana

**Single Controller
 Measured Usage History Report**



McGee & Associates

Landscape Architecture

Project: GOLDEN GATE BEAUTIFICATION, M.S.T.U.

Landscape Architect Report: January 2021

Location: Sunshine Blvd.

Project Manager: Dan Schumacher, Collier County Public Services Department, Public Transportation & Neighborhood Enhancements Division

Consultant's Representative: Michael A. McGee, rla, isa

Consultant: McGee & Associates

Contractor's Representative: Jeff Dulaney

Landscape Contractor: Mainscape

Observation Date: 01/04/2021

Report Date: 01/04/2021

Report No.: 3 (FY-21)

AC - Indicates major items recommended to be discussed by Advisory Committee **S** - Indicates items recommended to be addressed by staff, **C** - Indicates items recommended to be addressed by Contractor

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
					MONTHLY ADDRESSED	Yellow - Items recommended to be addressed as soon as possible or renovation recommendations generally based upon vehicular or storm damage.
All locations		X			Roadway replacement & ornamental tree pruning bid schedule being developed for pricing.	M&A: 01/04/21 replacement & pruning bid schedule under review & development.
		X		28	Median numbers on the ends of medians need to be refreshed.	
Median #1			X	55	On the north end about 60 L.F. of Juniper has been damaged. It appears to have been run over. Prune out damaged and dead foliage. (Photo)	M&A 11/12/18: Review Juniper bed for replacements.
			X	67	Two Juniper plants have been damaged and need to be replaced with 3 gal. size.	
Median #2		X	X	28	At address 2184: South end of Plumbago shrub bed needs to have dead plants removed and new plants installed. (9) 3 gal. size Plumbago.	M&A: 11-3-20 Remove remaining Plumbago and replant bed with (21) 3 gal. Bougainvillea 'Silhouette'.
		X	X	28	At address 2160: North end of Plumbago shrub bed needs to have dead plants removed and new plants installed. (5) 3 gal. size Plumbago.	M&A: 11-3-20 Remove remaining Plumbago and replant bed with (21) 3 gal. Bougainvillea 'Silhouette'.
		X	X	31	At address 2172: Plumbago shrub beds contain defoliated plants. Review for insects and prune out dead wood.	M&A: 1/7/19 Shrubs are dry and irrigation coverage needs to be reviewed, as well as possible additional heads added.
		X	X	37	At address 2052: Juniper runover. 4-5 plants damaged. Review to remove damaged or dead and provide count for replacements. 3 gal. size.	
	X	X		37	At address 2224: (1) Tabebuia 'Ipe' has lifted and needs to be reset. (1) Tabebuia 'Ipe' has been removed. Recommend replacement.	The Tabebuia if reset could use additional soil backfill around base to cover exposed root system. M&A: 09/11/18 Additional review of lifted Tabebuia tree has revealed upper canopy damage from hurricane Irma that will require the tree to be removed and replaced. M&A: 1/7/19: Install Tabebuia 'Ipe', 11'-13' ht., 3.5" cal., 5'-6' spr., 36" B&B or 65 Gal.
	X	X		37	At address 2184: (1) Tabebuia 'Ipe' has lifted and needs to be reset.	
	X	X		37	At address 2160: (2) Tabebuia 'Ipe' have been removed.	Alternate tree type could be considered (e.g, Crape myrtle) M&A: 1/7/19: Install Tabebuia 'Ipe', 11'-13' ht., 3.5" cal., 5'-6' spr., 36" B&B or 65 Gal.
	X	X		37	At address 2112: (1) Golden Tabebuia damaged. Remove and replace.	M&A: 1/7/19: Install Tabebuia 'Golden', 11'-13' ht., 3.5" cal., 5'-6' spr., 36" B&B or 65 Gal.
	X	X		37	At address 2112: (2) Tabebuia 'Ipe' damaged. Remove and replace.	Alternate tree type could be considered (e.g, Crape myrtle) M&A: 1/7/19: Install Tabebuia 'Ipe', 11'-13' ht., 3.5" cal., 5'-6' spr., 36" B&B or 65 Gal.
	X	X		37	At address 2101: (1) Golden Tabebuia damaged. Remove and replace.	M&A: 1/7/19: Install Tabebuia 'Golden', 11'-13' ht., 3.5" cal., 5'-6' spr., 36" B&B or 65 Gal.
			X	44	Address 2112: Replant (13) dwarf Bougainvillea 'Helen Johnson' 3 gal. size at location where water service repair occurred.	



McGee & Associates

Landscape Architecture

GOLDEN GATE BEAUTIFICATION, M.S.T.U.

Location: Sunshine Blvd.

Report Date: 01/04/2021

Report No.: 3 (FY21)

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
			X	76	At address 2274: Replace auto accident damaged Juniper on south end of median.	M&A: Appears 3-3 gal. plants will be needed. M&A: 7/8/14 another accident has occurred in same location. Approx. 50 L.F. of Juniper damaged. Review and remove damaged and provide count for replacements. M&A: 11-11-15 Review area and provide count for replacement Juniper 3 gal. size. (photo)
Median #3 - Pump Station Location- 5 hp, 6" well, VFD		X	X	37	At address 1991: Reset Tabebuia 'Ipe'.	
		X	X	37	At address 1960: Oak tree needs structural and corrective pruning.	
	X	X	X	37	At address 1944: (2) Tabebuia 'Ipe' damaged. Remove and replace.	Alternate tree type could be considered (e.g, Crape myrtle) M&A: 1/7/19: Install Tabebuia 'Ipe', 11'-13' ht., 3.5" cal., 5'-6' spr., 36" B&B or 65 Gal.
			X	37	At address 1944: (1) Silk Floss tree has upper trunk damage. Structural and corrective pruning needed to regrow main leader.	
	X	X	X	37	At address 1945: (2) Tabebuia 'Ipe' damaged. Remove and replace.	Alternate tree type could be considered (e.g, Crape myrtle) M&A: 1/7/19: Install Tabebuia 'Ipe', 11'-13' ht., 3.5" cal., 5'-6' spr., 36" B&B or 65 Gal.
		X	X	37	At address 1936: Oak tree needs structural and corrective pruning.	
		X	X	37	At address 1900: Oak tree needs structural and corrective pruning.	
			X	37	Address 1960 to 1944: Bougainvillea shrubs have been runover. Prune out damaged wood and provide count for replacements. (photo)	
			X	71	Light pole accident on south end of median. Multiple Juniper have been run over and are damaged and broken. Prune out damaged foliage and branches and review in 30 days for replacements.	M&A: 12-12-14 Damaged plants have been removed. M&A: 11-11-15 Review Juniper for replacement count and submit estimate.
Median #4						
Median #5		X	X	6	On north tip of median auto damage has occurred to the Juniper. Prune out damaged or dead foliage and provide count for replacements with 3 gal. size Juniper Parsoni.	
		X	X	37	Oak trees need structural and corrective pruning.	M&A: 5/7/28 Prune back branches a minimum of 4-feet away from fixture.
			X	37	Prune Oak tree branches away from light poles.	M&A 5-13-19: Light is being blocked by the Oak tree foliage.
Median #6			X	45	Address 1750: Remove (3) declined dwarf Bougainvillea and replant (3) dwarf Bougainvillea 'Helen Johnson' 3 gal. size. Review existing soil and plant roots for any issues.	
			X	49	At address 1771: Cut surface circling root. Cut to remove or cut minimum 1-inch wide section out of the center of the root.	
			X	54	Previous light pole accident has left some dead and damaged Juniper plants. Provide count and replacement proposal. (5-6) 3 gal. size replacements.	
18th Place SW Median		X	X	2	Sabal palms not pruned.	
	X	X	X	49	Auto accident damaged 10-15 plants (photo) Recommend removing all the Bougainvillea and replant median with Perennial Peanut "Ecoturf" variety in 1 gal. 12" o.c., 36" offset from back of curbing. If all is not approved then recommend doing area of damaged Bougainvillea. In either case hand watering will be required so it should be included in the proposal.	M&A: 12/01/19 Bougainvillea not pruned and median contains weeds.
18th Ave. S.W. Median		X	X	2	Sabal palms not pruned	

Commented [MAM2]:



Commented [MM3]:

Commented [MAM4]:



McGee & Associates

Landscape Architecture

GOLDEN GATE BEAUTIFICATION, M.S.T.U.

Location: Sunshine Blvd.

Report Date: 01/04/2021


Report No.: 3 (FY21)

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
		X	X	25	Weeds in perennial peanut.	The entire median weeds and Perennial peanut plants have been apparently killed with herbicide. M&A: 4/8/19 Median will be replanted in rainy season due to no irrigation. M&A: 9/9/19 Median replanted with perennial peanut, but plants look water stressed and bed contains weeds. M&A: 12/01/19 Median contains weeds. M&A: 03/01/20 Perennial peanut planting needs total replanting. M&A 7/8/20 Additionally, hand remove and spray weeds median where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. Plantings will need to be hand watered at planting and during supplement ally if rain is not occurring by tanker until established. M&A: 8/31/20 Median Ready for replanting.
QUARTERLY ADDRESSED						
Accent/Street Lighting						
Lighting Electric Meters & Irrigation Controller Electric Source Locations					Lighting Electric Meter 2271 Sunshine Blvd., 1 SUN, Alley off 23 rd Ave. SW Lighting Electric Meter & Irrigation Controller Electric, 1995 Sunshine Blvd., 2 SUN, Alley off 20 th PL. SW Lighting Electric Meter 4642 18 th Pl. SW, 3 SUN, North R/W	
Fertilizations:			X		Refer to FY20-21 schedule.	
Irrigation:					Previous month water use total per WeatherTrak controller estimate 175,439 gallons.	

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
--------------------	----	---	---	---	---	----------------------

Collier County
 Site: Golden Gate MTSU
 09013515 - 2002 Sunshine

**Single Controller
 Measured Usage History Report**



McGee & Associates

Landscape Architecture

Project: GOLDEN GATE BEAUTIFICATION, M.S.T.U.

Landscape Architect Report: January 2021

Location: Coronado Parkway & Hunter Blvd.

Project Manager: Dan Schumacher, Collier County Public Services Department, Public Transportation & Neighborhood Enhancements Division

Consultant's Representative: Michael A. McGee, rla, isa

Consultant: McGee & Associates

Contractor's Representative: Jeff Dulaney

Landscape Contractor: Mainscape

Observation Date: 01/04/2021

Report Date: 01/04/2021

Report No.: 3 (FY-21)

AC - Indicates major items recommended to be discussed by Advisory Committee **S** - Indicates items recommended to be addressed by staff, **C** - Indicates items recommended to be addressed by Contractor

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
					MONTHLY ADDRESSED	Yellow - Items recommended to be addressed as soon as possible or renovation recommendations generally based upon vehicular or storm damage.
Coronado Pkwy. - All locations		X			Roadway replacement & ornamental tree pruning bid schedule being developed for pricing.	
		X	X		Medians have had weeds sprayed and/or removed and renovation could begin.	
		X	X		All areas need mulch applied.	M&A: 3/1/20 Partial mulching has occurred.
		X	X	12	All Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A: 8/3/20 All weeds have been cut down and sprayed. Removal of large dead weed clumps and continued spraying will need to occur before replanting areas. M&A: 8/31/20 Locations have had weeds sprayed and/or removed and renovation could begin.
	X	X		30	Recommend that all paver areas be pressure washed following the irrigation conduit installation.	M&A: "Wet & Forget" test area recommended
		X		30	Median numbers need to be refreshed.	
		X	X	37	All canopy type trees need minor broken branches removed.	
Median #1- Pavers		X		36	Pressure cleaning recommended	
Median #2- Pavers		X		36	Pressure cleaning recommended	
Median #3			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand weed where existing Perennial peanut coverage exist and spray areas where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. M&A: 8/31/20 Locations have had weeds sprayed and/or removed and renovation could begin.
		X		28	North end Foxtail palm is in serious decline with no new center frond. Removal is recommended, and any replanting of a new Foxtail should include soil amendments to the backfill soil. If one more fertilization attempt is to be performed it is recommended to apply 3 lbs. per palm of Manganese Sulfate within a curb to curb and 10-foot north and south area away from the trunk.	M&A 11/12/18: Palm is dead and needs to be removed. Replacement is recommended with review of soil after removal for amendments. M&A: 12/01/19 Palm removed replacement recommended.
Median #4		X	X	4	The eastern four Alexander palms are missing from previous auto accidents. The 7th	

Design * Environmental Management * Planning * Arborist

5079 Tamiami Trail East / P. O. Box 8052 Naples, Florida 34101

Phone (239) 417-0707 * Fax (239) 417-0708

LC 098 * FL 1023A

<u>LOCATION/WORK AREA</u>	<u>AC</u>	<u>S</u>	<u>C</u>	<u>R</u>	<u>MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS</u>	<u>RESPONSE or COMMENTS</u>
					Alexander palm from the east end has been broke at the base. It appears to be an auto accident, but may have been from lightening. Replacement of all palms is recommended. (5) Alexander palm locations will need stumps removed and then replanted with 10 ft. clear trunk ht. min. palms.	
		X	X	6	The easternmost Alexander palm has been removed and needs to be replaced. Remove stump and replace with 10 ft. clear trunk size palm.	
			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray east and west median ends where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.
Median #5			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray weeds median where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.
Median #6			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray weeds on the east and west median ends where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms. Provide count of missing Yellow African Iris plants in the middle area of the median, 3 gal. size, 4' o.c., (12+/- plants needed).
Median #7			X	13	Juniper plantings need to be reviewed for replacements.	
Median #8		X	X	13	Juniper plantings need to be reviewed for replacements.	
Median #9 - Pavers		X		13	Pressure cleaning recommended	
Median #10			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray east and west median ends where

<u>LOCATION/WORK AREA</u>	<u>AC</u>	<u>S</u>	<u>C</u>	<u>R</u>	<u>MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS</u>	<u>RESPONSE or COMMENTS</u>
						existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.
				37	At address 5273: (2) Jatropha removed.	Consider replacement with alternate plant (e.g. Crape Myrtles) or leave unplanted and increase shrub or ground cover plantings. M&A: 7/9/18 Install (1) 15 gal. multi-stem shrub 4' ht.
	X	X	X	37	At address 5301: (2) Jatropha removed.	Consider replacement with alternate plant (e.g. Crape Myrtles) or leave unplanted and increase shrub or ground cover plantings. M&A: 7/9/18 Install (1) 15 gal. multi-stem shrub 4' ht.
	X	X	X	37	At address 5327: (2) Jatropha removed.	Consider replacement with alternate plant (e.g. Crape Myrtles) or leave unplanted and increase shrub or ground cover plantings. M&A: 7/9/18 Install (1) 15 gal. multi-stem shrub 4' ht.
Median #11 Bridge			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray east and west median ends where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.
Median #12			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray median where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.
			X	50	One Alexander palm on the east end of the median has been cut off at ground level. Replacement is recommended.	M&A: 10/7/16 Recommend replacement of Alexander palm, 10 ft. clear trunk ht. min.
Median #13		X	X	6	Additionally, hand remove and spray median to remove weeds where existing Society Garlic plants are located. Provide count for 1 gal. Society Garlic plants replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees.	
Median #14		X	X	6	Hand removal with herbicide applications during weekly services should address weed	

<u>LOCATION/WORK AREA</u>	<u>AC</u>	<u>S</u>	<u>C</u>	<u>R</u>	<u>MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS</u>	<u>RESPONSE or COMMENTS</u>
					issues in Blueberry Flax lily. Provide count for missing plants at 1 gal. size replacement plants.	
Hunter Blvd. - All locations		X			Roadway replacement & ornamental tree pruning bid schedule being developed for pricing.	
		X		12	All areas need mulch applied.	
		X		31	Median numbers need to be refreshed.	
		X	X	37	All canopy type trees need minor broken branches removed.	
Median #1		X	X	13	Juniper plantings need to be reviewed for replacements.	M&A 7/8/20 Hand removal with herbicide applications during weekly services should address weed issues in Juniper plants. Provide count for missing plants at 3 gal. size replacement plants. M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
Median #2		X	X	6	Additionally, hand remove and spray weeds on south end of median where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.	M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
			X	68	(3) Big Rose plant is dead.	Provide estimate for replacement at 1 gal. size. M&A: 4/15/15 Contractor is trying to locate a nursery supplier. M&A 7/9/18: Install (3) 1 or 3 gal. Crown of thorn 'Big Rose'
Median #3		X	X	6	Additionally, hand remove and spray weeds on south and north median ends where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.	M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
		X	X	6	Additionally, hand remove and spray weeds in Bougainvillea planting areas. Provide count of missing plants at 3 gal. size replacement plants.	M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
	X	X	X	36	Median received additional flooding during storm and planting bed soil has been removed. All shrub or ground cover plantings need to be removed. Median will need an additional 4 to 6-inch layer of soil added prior to any renovation planting work. Existing Alexander palms and Crape myrtles need additional soil placed around exposed root systems as soon as possible.	M&A: 7/9/18 Renovation Recommendation: Install by topdressing/backfilling entire median with clean native topsoil (85 c.y. +/-). Median soil profile to be 4-inch below top of curbing or pavers and elevate to 4" to 8" above curb along centerline of median.
Median #4		X	X	6	Additionally, hand remove and spray weeds in median where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.	M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
			X	39	Fourth Alexander palm from the north end has died. Please review for possible cause. Replacement should include fungicide soil drench.	M&A: Do not remove Alexander palm. New Frond has emerged from the bud. Treat with fungicide and fertilize with 4 lbs. 13-3-13 palm special fertilizer. M&A: 7/9/18 Install (1) Alexander palm 10' clear trunk. (24) 3 gal. Juniper 'Parsonii' at missing locations between palms. M&A: 8/3/20 Weeds have been addressed and replacements should be installed.


<u>LOCATION/WORK AREA</u>	<u>AC</u>	<u>S</u>	<u>C</u>	<u>R</u>	<u>MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS</u>	<u>RESPONSE or COMMENTS</u>
Median #5 Pump station – Median #5, 7.5 hp, 8" well feeds Hunter & Coronado, Irrinet in median controls Piccolos			X	13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray weeds on south and north median ends where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
Median #6		X	X	6	Additionally, hand remove and spray weeds on south median end where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.	M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
		X	X	6	Additionally, hand remove and spray north end of median to remove weeds where existing Society Garlic plants are located. Provide count for 1 gal. Society Garlic plants replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees.	M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
		X	X	24	At address 2007: Reset Oak.	
		X	X	24	At address 2043: Reset Oak.	
		X		30	Additional median flooding has washed soil onto the east and west roadways along the middle to south end of the median. Removal should occur as soon as possible.	
		X	X	37	At address 2116: Reset Oak.	
		X	X	37	At address 2100: Reset Oak.	
	X	X	X	37	At address 2018: (1) Jatropha removed.	Consider replacement with alternate plant or leave unplanted and increase shrub or ground cover plantings. M&A: 7/9/18 Install (1) 15 gal. multi-stem shrub 4" ht.
Median #7		X	X	6	Additionally, hand remove and spray median to remove weeds. Provide count of missing Yellow African Iris plants in median, 3 gal. size, 4' o.c., 2-3 feet off palms.	M&A: 8/3/20 Weeds have been addressed and replacements should be installed.
Median #8		X	X	6	On west end of median auto accident to streetlight pole and one Alexander palm. Remove damaged palm debris and stump and replace with 10 ft. clear trunk size palm.	
		X	X	6	Additionally, hand remove and spray existing weeds and vine throughout the median. Prune plants as required during normal weekly services.	M&A: 8/3/20 Weeds have been addressed through 50% of the median.
		X		13	At address 5375: Tree removed and planting hole open and coned off.	
		X		13	At address 5395 - 5390: Replacement Oak needs to be reviewed for replacement.	
		X		13	Perennial peanut plantings under weed control process.	Perennial Peanut plantings are not fully recovering. M&A: 3/1/20 Perennial Peanut plantings will need complete renovation plantings. M&A 7/8/20 Additionally, hand remove and spray weeds on east median end where existing perennial peanut was located. Provide count for 1

<u>LOCATION/WORK AREA</u>	<u>AC</u>	<u>S</u>	<u>C</u>	<u>R</u>	<u>MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS</u>	<u>RESPONSE or COMMENTS</u>
						gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.
		X	X	37	At address 5281: (1) Oak tree reset.	
	X	X	X	37	(1) Jatropha removed.	Consider replacement with alternate plant or leave unplanted and increase shrub or ground cover plantings. M&A: 7/9/18 Install (1) 15 gal. multi-stem shrub 4' ht.
		X	X	37	At address 5325: Oak tree reset.	
				37	(1) Jatropha removed.	Consider replacement with alternate plant or leave unplanted and increase shrub or ground cover plantings. M&A: 7/9/18 Install (1) 15 gal. multi-stem shrub 4' ht.
	X	X	X	37	(1) Jatropha removed.	Consider replacement with alternate plant or leave unplanted and increase shrub or ground cover plantings. M&A: 7/9/18 Install (1) 15 gal. multi-stem shrub 4' ht.
Median #9		X	X	6	Additionally, hand remove and spray weeds on east and west median ends where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees.	
		X	X	6	Additionally, hand remove and spray weeds in median Iris plantings. Provide count of missing and additional Yellow African Iris plants in the middle area of the median, 3 gal. size, 4' o.c.,	
	X	X	X	54	17 – Big Rose crown of thorn have been partially up rooted due to recent storm winds and/or fallen trees. It is recommended to dig, replant and hand water in plants. Cut back plants as required in order for plants to stand upright. 1 – Big Rose plant has been broken at base and needs to be replaced.	M&A: Additional storm damage to the crown of thorn has occurred. Recommend removal of all plants and replant median with dwarf Bougainvillea 'Helen Johnson' in 3 gal. size containers. Provide count and proposal recommended. M&A 7/9/18: Remove Big Rose install (68) Yellow African Iris 4' o.c., 4.5' off back of curbing in 3 rows.
Median #10		X	X	6	Additionally, hand remove and spray weeds median where existing perennial peanut was located. Provide count for 1 gal. Perennial peanut 'Ecoturf' replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. It is estimated there to be approximately (19) plants in two rows between Alexander palms.	
Median #11		X		7	Silk floss tree needs pruning for structure, thinning and shaping.	
		X	X	37	35 -40 Society Garlic plants are missing. Replacement recommended.	M&A 7/9/18: Install 40 Society Garlic plants, 1 gal., 24" o.c. in missing locations. Additionally, hand remove and spray median to remove weeds where existing Society Garlic plants are located. Provide count for 1 gal. Society Garlic plants replacements based upon 18 inches on center plantings located 4 feet off back of curbing and 3-foot radius off trees. M&A 7/8/20 Additionally, hand remove and spray median to remove weeds where existing Society Garlic plants are located. Provide count for 1 gal. Society Garlic plants replacements based upon 18 inches on center

LOCATION/WORK AREA	AC	S	C	R	MAINTENANCE SERVICES OBSERVATIONS & RECOMMENDATIONS	RESPONSE or COMMENTS
						plantings located 4 feet off back of curbing and 3-foot radius off trees.
Median #12		X	X	6	Hand removal with herbicide applications during weekly services should address weed issues in Blueberry Flax lily. Provide count for missing plants at 1 gal. size replacement plants.	
		X	X	6	The westernmost Alexander palm has been removed and needs to be replaced. Remove stump and replace with 10 ft. clear trunk size palm.	
QUARTERLY ADDRESSED						
Fertilization:			X		Refer to FY20-12 schedule.	
General Irrigation:			X		Previous month water use total per WeatherTrak controller estimate 89,573 gallons.	

Collier County
 Site: Golden Gate MTSU
 09105378 - 2003 Hunter Coronado

**Single Controller
 Measured Usage History Report**



SchumacherDan

From: MacFarlane, Tracy <Tracy.MacFarlane@fpl.com>
Sent: Friday, January 15, 2021 1:14 PM
To: SchumacherDan
Subject: Re: Golden Gate: Leaning Light Poles (FPL)

EXTERNAL EMAIL: This email is from an external source. Confirm this is a trusted sender and use extreme caution when opening attachments or clicking links.

Dan,

I viewed the WRs on Wednesday. 5 poles work orders were completed that indicated that they straightened poles.

2 work orders were completed and indicated that the poles were with limits.

1 work order is still open.

On Jan 15, 2021, at 12:55 PM, SchumacherDan <Dan.Schumacher@colliercountyfl.gov> wrote:

Caution - External Email (dan.schumacher@colliercountyfl.gov)

[Report This Email](#)

[Tips](#)

Tracy,

Preparing for the Advisory Committee meeting next Tuesday, 1/19.

- Did you receive verification that the poles have been straightened?

Please advise.

Respectfully,

-Dan Schumacher
(239) 252-5775
MSTU Project Manager
Public Transit & Neighborhood Enhancement Division
Public Services Department

From: MacFarlane, Tracy <Tracy.MacFarlane@fpl.com>
Sent: Wednesday, December 9, 2020 2:00 PM
To: SchumacherDan <Dan.Schumacher@colliercountyfl.gov>
Subject: RE: Golden Gate: Leaning Light Poles (FPL)

Dan,