Prjct Mgr: Darryl Richard Bid #08-5027 " Bayshore Drive Bridge Lighting Landscape Installation" Date Posted: 5/27/08

Date Due: 6/26/08

Notices Sent: 671 Packages Downloaded: 63 Bids Received: 3 Non-Responsive: 1

				E.B. Simmonds	Electrical Inc	Kent Techno	ologies II.C
Item #	Item Description	Unit	Qty	Unit Price	Total	Unit Price	Total
	Pole Lumec RAF802-12-GN-TX Single Sided Arms	Ea	17	\$1,502.60	\$25,544.20	\$2,263.00	\$38,471.00
	Pole Lumec RAF805-12-GN TX Double Sided Arms	Ea	4	\$1,619.20	\$6,476.80	\$2,366.00	\$9,464.00
	Remove Existing Luminaries	LS	1	\$4,021.50	\$4,021.50	\$8,454.00	\$8,454.00
	GFI Receptacles	LS	1	\$180.32	\$180.32	\$523.00	\$523.00
	Pull 3-#10 THHN wire	LS	1	\$1,073.70	\$1,073.70	\$1,900.00	\$1,900.00
	Revise existing service	LS	1	\$693.00	\$693.00	\$2,200.00	\$2,200.00
	Install new conductors	LS	1	\$1,155.00	\$1,155.00	\$1,302.00	\$1,302.00
	Replace break away inline fuse holders	LS	1	\$3,676.09	\$3,676.09	\$4,069.00	\$4,069.00
	Deliver & Store 10' poles to Owner	LS	1	\$1,261.54	\$1,261.54	\$346.00	\$346.00
	MOT	LS	1	\$9,680.00	\$9,680.00	\$3,246.00	\$3,246.00
10	Total Base Bid	LO		ψ0,000.00	\$53,762.15	ψ5,2-10.00	\$69,975.00
	Total base blu				ψ55,702.15		ψ09,913.00
11	Foxtail Palm	Ea	8	\$318.00	\$2,544.00	\$462.00	\$3,696.00
12	Pygmy Date Palm	Ea	15	\$212.00	\$3,180.00	\$346.00	\$5,190.00
13	Euphorbia	Ea	150	\$5.30	\$795.00	\$8.00	\$1,200.00
14	Dwarf Indian Hawthorn	Ea	44	\$8.48	\$373.12	\$12.00	\$528.00
15	Shillings Holly	Ea	15	\$8.48	\$127.20	\$12.00	\$180.00
16	White Fountain Grass	Ea	83	\$8.48	\$703.84	\$12.00	\$996.00
17	Prepare site for planting	LS	1	\$2,385.00	\$2,385.00	\$3,462.00	\$3,462.00
18	Test & Inspect irrigation	LS	1	\$2,544.00	\$2,544.00	\$3,692.00	\$3,692.00
	Repair and Replace irrigation	LS	1	\$2,968.00	\$2,968.00	\$4,308.00	\$4,308.00
20	MOT	LS	1	\$689.00	\$689.00	\$1,000.00	\$1,000.00
	Total of Alternate				\$16,309.16		\$24,252.00
	Total Base + Alternate				\$70,071.31		\$94,227.00
	A 1						
	Agent:						
	Witness:						
	Wall Systems Inc. of SWFL d/b/a Professional Building Systems deemed non-responsive - bond not included						
	Material Manufacturers				Y		Y
	List of Subcontractors				Y		Y
	Statement of Experience of Bidder				Y		<u>'</u> Ү
	Trench Safety Act				Y		<u>'</u> Ү
	Bid Bond				Y		
	Bidder Check List				Y		<u>т</u> Ү
	Contractor Pre-Qualification Form (Safety)				Y		Y
	Contractor r re-Qualification r offir (Safety)				ı		<u> </u>
	LAP Funded						