









































March 17, 2009 Date: Inspection: Inspected by: Pine Air Lakes

Mark Lindsay, Denise Weaver

Begin: Naples Blvd.

Location	Deficiency	Picture#
Naples Blvd. at Pine Ridge intersection-turn lanes north of Home Depot	 Asphalt not pinched over, various locations / Needs to be sealed Curbing in good condition / If damaged due to irrigation line construction, the contractor (Stahlman) will be responsible for repairs 	3567-69 3570
Naples Blvdturn lanes at Home Depot	 Asphalt not pinched over, various locations / Needs to be sealed Cracked curbing / Replace in 4' min. sections Cracked curbing / Replace in 4' min. sections, add expansion joint (various locations) Curbing in good condition / If damaged due to irrigation line construction, the contractor (Stahlman) will be responsible for repairs Painted striping will be rechecked at 1 yr. warranty 	3571 3572 3573-76 3577 3583
Pork chop at Home Depot	- Additional striping, delineators & signage (No Left Turn) is required by Design Standards	3578
Naples Blvdmedian at Home Depot	- Curbing in good condition / If damaged due to irrigation line construction, the contractor (Stahlman) will be responsible for repairs	3579
Pine Ridge Rd. at Naples Blvd. intersection -eastbound turn lanes	Needs 3 expansion joints for 10' spansAdd chain to inlet	3580-81 3582
Naples Blvd. at Airport Rd. intersection	 Slight depression (3/8" for 100' +/-) will be rechecked at final & 1 yr. warranty / May require mill and resurface Cracked curbing / Replace in 4' min. sections, add expansion joint (various locations) Asphalt not pinched over, various locations / Needs to be sealed 	3584 3585 3586
Airport Rd. at Naples Blvd. intersection	- Curbing needs to be sealed	3587

- All median landscaping will be contractor's responsibility
- CEI will periodically recheck curbing to ensure no further damage due to irrigation subcontractor's negligence