

LELY MSTU LIGHTING INSPECTIONS

Inspection date: 3-24-15 _____

ST. ANDREWS ENTRANCE OFF US41

LIGHT DESCRIPTION	SHEET#	ON: yes/no; Y/N	Notes:
Flagpole Light-1	1	Y	
Flagpole Light-1	1	Y	
Flagpole Light-1	1	Y	
Sign Light-North US41	1	Y	
Sign Light-South US41	1	Y	
Single Luminaire-1	1	Y	
Single Luminaire-2	1	Y	
Single Luminaire-3	1	Y	
Single Luminaire-4	1	Y	
Single Luminaire-5	1	N	
Single Luminaire-6	1	Y	
Single Luminaire-7	1	Y	
Single Luminaire-8	1	N	
Single Luminaire-9	1	Y	
Single Luminaire-10	1	Y	
Single Luminaire-11	1	Y	

PEBBLE BEACH LIGHTING

Double Luminaire-1	2	Y	
Double Luminaire-2	2	Y	
Double Luminaire-3	2	Y	
Double Luminaire-4	2	Y	
Double Luminaire-5	2	Y	
Double Luminaire-6	2	Y	
Double Luminaire-7	2	Y	
Double Luminaire-8	2	Y	
Double Luminaire-9	2	Y	
Double Luminaire-10	3	Y	
Double Luminaire-11	3	Y	
Double Luminaire-12	3	Y	
Double Luminaire-13	3	Y	
Double Luminaire-14	3	Y	
Double Luminaire-15	3	Y	
Double Luminaire-16	3	Y	
Double Luminaire-17	3	Y	
Double Luminaire-18	3	Y	
Double Luminaire-19	3	Y	
Double Luminaire-20	4	Y	
Double Luminaire-21	4	Y	
Single Luminaire-22	4	Y	
Single Luminaire-23	4	Y	

SOLAR LIGHT @ AUGUSTA

Solar Light-@Augusta	5	Y
----------------------	---	---

DORAL CIRCLE LIGHTING

Double Luminare-D-1	6	N
---------------------	---	----------

Double Luminare-D-2	6	N
---------------------	---	----------

Sign Light-DS-1	6	Y
-----------------	---	---

Sign Light-DS-2	6	Y
-----------------	---	---

Single Luminare-B1	7	N
--------------------	---	----------

Single Luminare-B2	7	N
--------------------	---	----------

Single Luminare-B3	7	N
--------------------	---	----------

Single Luminare-B4	7	N
--------------------	---	----------