Randall Boulevard Corridor Study

Improved/Unimproved Parcels

Randall Blvd and Oil Well Rd
CORRIDOR STUDY

SECTION 1



29% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 2



29% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 3



79% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 4



46% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 5



41% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 6



37% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 7



54% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 8



50% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 9



46% Occupied
- Vacant Parcel
- Occupied Parcel

SECTION 10



36% Occupied
- Vacant Parcel
- Occupied Parcel