

Lely Beautification MSTU

| <i>LELY MSTU LIGHTING INSPECTION</i> | | <i>Inspection Date:</i> | | | <i>10/03/2019</i> | |
|---|-----------|--------------------------------|----------|----------|--------------------------|----------|
| ST. ANDREWS ENTRANCE - FROM US-41 | | | | | | |
| TUBE | | A | B | C | D | E |
| Sign - Enter | 1 | | | | | |
| Sign - Exit | 2 | | | | | X |
| SPOT | | ○ | A | B | Notes | |
| Flagpole - US | 1 | | | | | |
| Flagpole - FL | 2 | | | | | |
| Flagpole - BCC | 3 | | | | | |
| LUMINAIRE | | ○ | A | B | | |
| Single | 1 | | | | | |
| Single | 2 | | | | | |
| Single | 3 | | | | | |
| Single | 4 | | | | | |
| Single | 5 | | | | | |
| Single | 6 | | | | | |
| Single | 7 | | | | | |
| Single | 8 | | | | | |
| Single | 9 | | | | | |
| Single | 10 | | | | | |
| Single | 11 | | | | | |
| PEBBLE BEACH BLVD | | | | | | |
| LUMINAIRE | | ○ | A | B | | |
| Double | 1 | | | | | |
| Double | 2 | | | | | |
| Double | 3 | | | | | |
| Double | 4 | | | | | |
| Double | 5 | | | | | |
| Double | 6 | | | | | |
| Double | 7 | | | | | |
| Double | 8 | | | | | |
| Double | 9 | | | | | |
| Double | 10 | | | | | |
| Double | 11 | | | | | |
| Double | 12 | | | | | |
| Double | 13 | | | | | |
| Double | 14 | | | | | |
| Double | 15 | | | | | |
| Double | 16 | | | | | |
| Double | 17 | | | | | |
| Double | 18 | | | | | |
| Double | 19 | | | | | |
| Double | 20 | | | | | |
| Double | 21 | | | | | |
| Single | 22 | | | | | |
| Single | 23 | | | | | |

1909

Lely Beautification MSTU

| <u>LELY MSTU LIGHTING INSPECTION</u> | | | | | <u>Notes</u> | |
|---|----|---|---|---|---------------------|--|
| FOREST HILLS @ AUGUSTA | | | | | | |
| 'LELY' SIGN | | ● | A | B | | |
| Solar Light | -- | | | | | |
| DORAL CIRCLE | | | | | | |
| TUBES | | ● | A | B | | |
| Sign - Enter | 1 | | | | | |
| Sign - Exit | 2 | | | | | |
| LUMINAIRE | | ● | A | B | | |
| Double | 1 | | | | | |
| Double | 2 | | | | | |
| Single | 3 | | | | | |
| Single | 4 | | | | | |
| Single | 5 | | | | | |
| Single | 6 | | | | | |

1909